


Montgomery County Public Schools

2018 School Facilities Assessment

School Number **513**
 School Name **Belmont**
 School Type **Elementary School**
 Year Built* **1974**
 Year of Last Renovation* **Unknown**
 GSF* **49,279**



Building Level - Key Facility Indicators



Infrastructure - Facility Condition

● A10 Foundations	n/a	● C20 Stairs	● D50 Electrical
n/a A20 Basement	●	● C30 Interior Finishes	● E10 Equipment
● B10 Superstructure	n/a	● D10 Conveying Systems	● E20 Furnishings
● B20 Exterior Enclosure	●	● D20 Plumbing	● F10 Special Construction
● B30 Roofing	●	● D30 HVAC	
● C10 Interior Construction	●	● D40 Fire Protection	

Building Characteristics

Building Quality	Indoor Environment
● Classroom Shape*	● Temperature Control
● IMC Size*	● Humidity Control
● Cafeteria Size*	● Natural Light
● Corridor*	● Acoustic Features
	● Building-Level Power Delivery

*indicates that underlying data was provided by MCPS not collected by FEA.

Information Sources:	(References)
----------------------	--------------