

936 RIDGEBROOK ROAD • SPARKS, MD 21152 • 410-316-7800 • (FAX) 410-316-7935

MCPS RADON TESTING – EXECUTIVE SUMMARY

Site Name	Rockville High School	
Date of Test Report	05/12/2022	
Round of Testing	<u>Initial</u>	
	Follow-up	
	Post Remediation	
	2 Year Testing	
	5 Year Testing	
	HVAC Upgrade	
	Window Replacement	
	New Addition	
	New Facility	
# Rooms Tested	1	
# Rooms \geq 4.0 pCi/L	0	
Lowest Value	<0.3 pCi/L	
Highest Value	<0.3 pCi/L	

Project Status

Current Project Status at this time: Testing completed; no further action needed

KCI Technologies, Inc. WWW.kci.com

ENGINEERS • PLANNERS • SCIENTISTS • CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD • SPARKS, MD 21152 • 410-316-7800 • (FAX) 410-316-7935

May 12, 2022

Mr. Brian Croyle, PG, CHMM Environmental Specialist Montgomery County Public Schools Gaithersburg, MD 20879

Re: Radon Testing Services

KCI Job # 122108316

Location: Rockville High School

2100 Baltimore Rd. Rockville, MD 20851

Dear Mr. Croyle:

KCI Technologies, Inc. (KCI) is pleased to submit the following report to Montgomery County Public Schools (MCPS) pursuant to completing a "short-term" 3 day radon test for the Rockville High School, located at 2100 Baltimore Rd. Rockville, MD 20851 (subject site).

Scope of Services:

KCI conducted radon testing at the subject site to evaluate indoor radon levels relative to the USEPA's recommended action level of 4.0 picocuries per Liter (pCi/L) - the level at which EPA recommends that schools take action to reduce the level. KCI conducted the radon testing in accordance with American Association of Radon Scientists and Technologists (AARST) *Protocol for Conducting Measurements of Radon and Radon Decay Products in Schools and Large Buildings*. A National Radon Proficiency Program (NRPP) Radon Measurement Specialist (certification #111004 RT) supervised the testing. Additional information on radon management and the health effects of radon exposure is available from https://www.montgomeryschoolsmd.org or www.epa.gov/radon.

KCI visited the site on March 22, 2022 and deployed three (3) activated charcoal (AC) radon test kits. KCI deployed radon test kits in all frequently-occupied ground contact rooms, and other areas, (if applicable) in accordance with AARST guidance.

KCI sampled the following locations during this follow-up test:

- 1. Rooms with missing test kits from the Radon 2022 testing period (i.e. test kit was deployed but not recovered),
- 2. Rooms with invalidated test kits from the Radon 2022 testing period (e.g. an open window in the room or disturbed test kit),
- 3. Rooms which were locked/inaccessible during the Radon 2022 testing period,
- 4. Rooms with elevated radon results (i.e. \geq 3.5 piC/L),
- 5. Rooms previously tested for radon but not tested in Radon 2022, and
- 6. Additional rooms that require testing (if applicable.)

A floor plan map of the building with the test locations is included as Attachment A of this report.

As a quality control measure, KCI also included duplicate samples, field blanks, lab transit blanks, and office blanks in accordance with AARST recommendations. In addition, KCI submitted test kits to Bowser-Morner, Inc. as spike samples. The spiked tests were exposed to a known radon concentration by Bowser-Morner prior to being returned to the laboratory for analysis.

KCI returned to the site on March 25, 2022 to retrieve the radon sampling test kits. KCI shipped all radon tests via overnight delivery to Airchek, Inc. for analysis by gamma-ray spectroscopy. Airchek, Inc. is a NRSB certified analytical laboratory for radon analysis (certification # ARL1402) located at 1936 Butler Bridge Road, Mills River, North Carolina.

Evaluation of Testing Conditions:

These tests represent:

• Follow-up to initial testing.

These tests were conducted to:

• Evaluate radon concentrations at the facility.

According to AARST, Protocol for Conducting Measurements of Radon and Radon Decay Products in Schools and Large Buildings, ideal testing conditions would be when the building is fully occupied and the heating system is active. For this test, the facility's HVAC system was operating in heating mode; therefore, KCI concludes that this test was conducted during ideal testing conditions.

KCI recorded observations of the following conditions in each room during the time of deployment and collection of the radon test kits:

- Indoor temperature,
- HVAC Operation,
- Dehumidifier operation,
- Humidifier operation,
- Ceiling fan operation, and
- Open windows or doors.

KCI also compiled weather data for the testing period and conducted observations of relevant field conditions. During the test period, weather records indicate low temperatures were in the low 40°Fs and high temperatures ranged from the low 50°Fs to the low 70°Fs. Maximum sustained winds ranged from 0-29 miles per hour. Average humidity was around 56% with 0.51 inches of precipitation (rain) was recorded during testing period.

Results:

The sampling locations and analytical results are listed on Table 1 (Attachment B). The quality control sample locations and analytical results are listed on Table 2 (Attachment B). Sampling locations and associated test kit identification numbers and relevant field observations are listed on Table 3 (Attachment B). The laboratory analytical results are included in Attachment C. Laboratory results and exposure data for the spike samples are also included in Attachment C.

KCI Technologies, Inc. www.kci.com

The results of the radon test analysis indicated the following:

Radon Concentration	Room	Result
≥4.0 piC/L	None	N/A
<4.0 piC/L	See Attachment B	

Quality Control Samples		
Results of Blank Canisters:	The office blanks, and lab transit blanks had test results of	
	less than the laboratory detection limit of 0.3 pCi/L.	
Adequate Laboratory Precision?	Review of the duplicate sample analysis indicates that	
	adequate laboratory measurement precision was achieved.	
Spike Sample Analysis:	The Spike Sample analysis results indicate the laboratory is	
	operating within statistical control limits.	

Our professional services have been performed in accordance with customary principles and practices in the field of industrial hygiene and engineering. If you have any questions or comments regarding this report, please feel free to contact me at (410) 891-1769.

Sincerely,

Tyler P. McCleaf

Radon Measurement Provider

#111004 RT

KCI Technologies, Inc.

Tyler McCleaf

Attachments: A- Floor Plan with Test Locations

B- Table 1-3, Radon Test Summary Spreadsheets

C- Laboratory Analytical Results

ATTACHMENT A

Floor Plan With Test Locations

ATTACHMENT B

Radon Test Summary Spreadsheet

Table Notes:

AC- Activated Charcoal

ACI- Air Check, Inc.

D- Duplicate

FB- Field Blank

KCI- KCI Technologies, Inc.

OB- Office Blank

PM- Project Manager

OC- Quality Control

Table 1- Radon Testing Results				
	Rockville HS RT			
Te	est Period: 03/22/2022 - 03/25/2022			
Kit Number	Room / Area	Result		
11131719	1001	< 0.3		
11131720	1001	< 0.3		
11131754	1001	< 0.3		

Table 2- Radon Testing Results				
	Rockville HS RT			
Test Period: 03/22/2022 - 03/25/2022				
Kit Number	QC Type	Room / Area	Result	
11131754	D	1001	< 0.3	
11131719	FB	1001	< 0.3	
11139902	ОВ	OFFICE BLANK	< 0.3	
11139928	ТВ	TRAVEL BLANK	< 0.3	

Summary of Missed Locations			
Rockville HS RT			
Test Period: 03/22/22 - 03/25/22			
Kit Number	Room/Area	Result	
	NA		

Summary of Missing, Compromised and >/= 4 piC/L Tests		
Rockville HS RT		
Test Period: 03/22/22 - 03/25/22		
Kit Number	Room/Area	Result
	NA	

Table Note:

^{*} Missing or Compromised Sample

ATTACHMENT C

Laboratory Analytical Results

** LABORATORY ANALYSIS REPORT **

Radon test result report for: **ROCKVILLE HS**

1	Analyzed	pCi/L	Ended	Started	Room Id	Kit#
11131720 1001 2022-03-22 @ 1:00 pm 2022-03-25 @ 12:00 pm < 0.3	2022-03-28	< 0.3	2022-03-25 @ 12:00 pm	2022-03-22 @ 1:00 pm	1001	11131754
	2022-03-28	< 0.3	2022-03-25 @ 12:00 pm	2022-03-22 @ 1:00 pm	1001	11131720
11131719 1001 2022-03-22 @ 1:00 pm 2022-03-25 @ 12:00 pm < 0.3	2022-03-28	< 0.3	2022-03-25 @ 12:00 pm	2022-03-22 @ 1:00 pm	1001	11131719

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

EXPOSURE IN BOWSER-MORNER RADON CHAMBER

CLIENT KCI Technologies, I	10b Number 204620
NOMINAL Conditions: Radon Conc 27. 0 p	Ci/L Rel. Hum <u>50.1</u> % Temp. <u>70.0</u>
Date Start: 3/18/22 Date Stop: 3/21/22	Date Start: Date Stop:
Time Start: <u>0795</u> Time Stop: <u>0795</u>	(
Device No.'s: (5) Char Bags-	Device No.'s:
11139367 11139368, 11139371,	
11139710, 11139717	C
E3 Right	
Date Start: Date Stop:	Date Start: Date Stop:
Time Start: Time Stop:	Time Start: Time Stop:
Device No.'s:	Device No.'s:
	ř
* a	
Date Start: Date Stop:	Date Start: Date Stop:
Time Start: Time Stop:	Time Start: Time Stop:
Device No.'s:	Device No.'s:

Note: All times are in 24-hour (military) notation, Eastern Standard Time (EST) Background = $7 \mu R/h$ Elevation = 820 ft

** LABORATORY ANALYSIS REPORT **

Radon test result report for:

MCPS - Spike Sample Lab Results. Measured values are satisfactory, i.e., within \pm 25% of the chamber's reference value (25.7 pCi/L).

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11139367	SK1	2022-03-18 @ 7:00 am	2022-03-21 @ 7:00 am	25.9 ± 2.1	2022-03-30
11139368	SK2	2022-03-18 @ 7:00 am	2022-03-21 @ 7:00 am	23.9 ± 2.0	2022-03-30
11139371	SK3	2022-03-18 @ 7:00 am	2022-03-21 @ 7:00 am	25.7 ± 2.1	2022-03-30
11139710	SK4	2022-03-18 @ 7:00 am	2022-03-21 @ 7:00 am	26.4 ± 2.1	2022-03-30
11139717	SK5	2022-03-18 @ 7:00 am	2022-03-21 @ 7:00 am	24.6 ± 2.0	2022-03-30

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498



Engineers • Planners • Scientists • Construction Managers

Corporate Office: 936 Ridgebrook road • Sparks , Maryland 21152 • 410-316-7800 • (Fax) 410-316-7935

Radon Test Kit Chain of Custody

Project Name: MCPS Radon - March 2022 Schools - Retesting

Name of Schools:

- 1. Herbert Hoover MS
- 2. Parkland MS
- 3. Redland MS
- 4. Rock Creek Valley ES
- 5. Tilden MS
- 6. Rockville HS
- 7. Wootton HS
- 8. Capt. James E. Daly ES
- 9. Clarksburg HS
- 10.Clearspring ES
- 11. Hallie Wells MS
- 12.Northwest HS
- 13. Paint Branch HS
- 14.Rocky Hills MS
- 15.Seneca Valley HS
- 16.Sherwood HS
- 17. Wilson Wims ES

	Date	Initials
Radon Test Kits Deployed	03/22/2022	SMM
Radon Test Kits Collected	03/25/2022	BMM
Radon Test Kits Shipped to Lab*	03/25/2022	BMM
Radon Test Kits Received by Lab*	03/28/2022	BIMM

^{*}All samples sent to Air Check, Inc., 1936 Butler Bridge Rd, Mills River, NC 28759



936 RIDGEBROOK ROAD • SPARKS, MD 21152 • 410-316-7800 • (FAX) 410-316-7935

MCPS RADON TESTING – EXECUTIVE SUMMARY

Site Name	Rockville High
	School
Date of Test Report	4/6/2022
Round of Testing	Initial
	Follow-up
	Post Remediation
	2 Year Testing
	5 Year Testing
	HVAC Upgrade
	Window Replacement
	New Addition
	New Facility
# Rooms Tested	117
# Rooms \geq 4.0 pCi/L	0
Lowest Value	<0.3 pCi/L
Highest Value	1.1 pCi/L

Project Status:

Initial testing completed; Missing or compromised kits need re-sampling.

KCI Technologies, Inc. WWW.kci.com



ENGINEERS • PLANNERS • SCIENTISTS • CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD • SPARKS, MD 21152 • 410-316-7800 • (FAX) 410-316-7935

April 6, 2022

Brian T. Croyle, PG, CHMM Environmental Specialist Montgomery County Public Schools Gaithersburg, MD 20879

Re: Radon Testing Services

KCI Job # 122108316

Location: Rockville HS

2100 Baltimore Rd. Rockville, MD 20851

Dear Mr. Croyle:

KCI Technologies, Inc. (KCI) is pleased to submit the following report to Montgomery County Public Schools (MCPS) pursuant to completing a "short-term" 3 day radon test for the Rockville HS, located at 2100 Baltimore Rd. Rockville, MD 20851 (subject site).

Scope of Services:

KCI conducted radon testing at the subject site to evaluate indoor radon levels relative to the USEPA's recommended action level of 4.0 picocuries per Liter (pCi/L) - the level at which EPA recommends that schools take action to reduce the level. KCI conducted the radon testing in accordance with American Association of Radon Scientists and Technologists (AARST) *Protocol for Conducting Measurements of Radon and Radon Decay Products in Schools and Large Buildings*. A National Radon Proficiency Program (NRPP) Radon Measurement Specialist (certification #111004 RT) supervised the testing. Additional information on radon management and the health effects of radon exposure is available from https://www.montgomeryschoolsmd.org or www.epa.gov/radon.

KCI visited the site on February 7, 2022 and deployed one hundred and thirty five (135) activated charcoal (AC) radon test kits. KCI deployed radon test kits in all frequently-occupied ground contact rooms, and other areas, (if applicable) in accordance with AARST guidance.

A floor plan map of the building with the test locations is included as Attachment A of this report.

As a quality control measure, KCI also included duplicate samples, field blanks, lab transit blanks, and office blanks in accordance with AARST recommendations. In addition, KCI submitted test kits to Bowser-Morner, Inc. as spike samples. The spiked tests were exposed to a known radon concentration by Bowser-Morner prior to being returned to the laboratory for analysis.

KCI returned to the site on February 10, 2022 to retrieve the radon sampling test kits. KCI shipped all radon tests via overnight delivery to Airchek, Inc. for analysis by gamma-ray spectroscopy. Airchek, Inc.

KCI Technologies, Inc. www.kci.com

is a NRSB certified analytical laboratory for radon analysis (certification # ARL1402) located at 1936 Butler Bridge Road, Mills River, North Carolina.

Evaluation of Testing Conditions:

These tests represent:

• Follow-up to initial testing.

These tests were conducted to:

• Evaluate radon concentration levels at the facility.

According to AARST, Protocol for Conducting Measurements of Radon and Radon Decay Products in Schools and Large Buildings, ideal testing conditions would be when the building is fully occupied and the heating system is active. For this test, the facility's HVAC system was operating in heating mode; therefore, KCI concludes that this test was conducted during ideal testing conditions.

KCI recorded observations of the following conditions in each room during the time of deployment and collection of the radon test kits:

- Indoor temperature,
- HVAC Operation,
- Dehumidifier operation,
- Humidifier operation,
- Ceiling fan operation, and
- Open windows or doors.

KCI also compiled weather data for the testing period and conducted observations of relevant field conditions. During the test period, weather records indicate low temperatures were in the 30s and high temperatures ranged from the mid 30s to the mid 50s Fahrenheit. Maximum sustained winds ranged from 3-12 miles per hour. Average humidity was around 23% with 0.1 inches of precipitation (rain) was recorded during testing period.

Results:

The sampling locations and analytical results are listed on Table 1 (Attachment B). The quality control sample locations and analytical results are listed on Table 2 (Attachment B). Sampling locations and associated test kit identification numbers and relevant field observations are listed on Table 3 (Attachment B). The laboratory analytical results are included in Attachment C. Laboratory results and exposure data for the spike samples are also included in Attachment C.

The results of the radon test analysis indicated the following:

Radon Concentration	Room	Result
≥4.0 piC/L	None	N/A
<4.0 piC/L	See Attachment B	

KCI TECHNOLOGIES, INC. WWW.kci.com

Quality Control Samples		
Results of Blank Canisters: The office blanks, and lab transit blanks had test results		
less than the laboratory detection limit of 0.3 pCi/L.		
Adequate Laboratory Precision?	Review of the duplicate sample analysis indicates that	
	adequate laboratory measurement precision was achieved.	
Spike Sample Analysis:	The Spike Sample analysis results indicate the laboratory is	
operating within statistical control limits.		

Our professional services have been performed in accordance with customary principles and practices in the field of industrial hygiene and engineering. If you have any questions or comments regarding this report, please feel free to contact me at (410) 891-1769.

Sincerely,

Tyler P. McCleaf

Tyler McCleaf

Radon Measurement Provider

#111004 RT

KCI Technologies, Inc.

Attachments: A- Floor Plan with Test Locations

B- Table 1-3, Radon Test Summary Spreadsheets

C- Laboratory Analytical Results

ATTACHMENT A

Floor Plan With Test Locations

ATTACHMENT B

Radon Test Summary Spreadsheet

Table Notes:

AC- Activated Charcoal

ACI- Air Check, Inc.

D- Duplicate

FB- Field Blank

KCI- KCI Technologies, Inc.

OB- Office Blank

PM- Project Manager

OC- Quality Control

Table 1- Radon Testing Results	
Rockville HS	

Test Period: 02/7/2022 - 02/10/2022

Kit Number	Room / Area	Result
11113403	1000	< 0.3
11113401	1001	< 0.3
11113402	1001	NA
11105831	1002	< 0.3
11113438	1003	< 0.3
11113437	1005	0.5
11113423	1011	0.6
11113435	1012	0.6
11113421	1013	< 0.3
11113422	1013	< 0.3
11113420	1015	< 0.3
11113419	1017	0.8
11113418	1019	< 0.3
11113436	1020	0.7
11113417	1021	0.6
11113431	1022	0.6
11113432	1022	< 0.3
11113433	1022	< 0.3
11113416	1023	< 0.3
11113430	1024	< 0.3
11113415	1025	0.8
11113414	1027	0.7
11113434	1029	< 0.3
11113429	1030	< 0.3
11113428	1032	< 0.3
11113409	1033	0.7
11113408	1035	0.8
11113427	1036	0.6
11113407	1037	0.6
11113426	1038	0.5
11113406	1039	0.8
11113455	1049	0.5
11113469	1050	< 0.3
11105897	1054	0.6
11105899	1054	< 0.3
11105891	1057	< 0.3
11105892	1057	0.7
11105893	1057	< 0.3
11105894	1059	< 0.3
11105895	1060	< 0.3
11105844	1062	1.1
11113456	1067	0.8

Table 1- Radon Testing Results	
Rockville HS	

Test Period: 02/7/2022 - 02/10/2022

Kit Number	Room / Area	Result
11105845	1069	0.5
11105846	1070	0.8
11105848	1071	0.6
11105849	1073	0.7
11105850	1075	< 0.3
11105852	1076	< 0.3
11105853	1076	0.6
11105854	1076	0.8
11105851	1077	< 0.3
11105858	1080	< 0.3
11105863	1081	< 0.3
11105859	1083	< 0.3
11105862	1083	< 0.3
11105867	1084	< 0.3
11105873	1084	< 0.3
11105871	1087	0.6
11105872	1087	0.6
11105875	1089	< 0.3
11105876	1091	0.6
11105877	1093	0.5
11105878	1095	0.9
11105889	1097	0.7
11105890	1097	0.6
11105882	1101	< 0.3
11105880	1103	0.7
11105881	1103	< 0.3
11105883	1105	0.7
11105887	1107	0.9
11105888	1109	0.7
11113466	2010	< 0.3
11113465	2014	< 0.3
11113462	2017	< 0.3
11113463	2017	< 0.3
11113464	2017	< 0.3
11113467	2067	0.5
11113461	2071	< 0.3
11113460	2091	0.8
11113459	2099	< 0.3
11113457	2114	< 0.3
11113458	2115	< 0.3
11113468	3039	< 0.3
11113405	1000B	< 0.3

Table 1- Radon Testing Results	
Rockville HS	

Test Period: 02/7/2022 - 02/10/2022

Kit Number	Room / Area	Result
11113404	1000C	< 0.3
11105832	1002A	< 0.3
11105833	1002B	< 0.3
11105834	1002C	< 0.3
11105835	1002D	< 0.3
11105836	1002D	< 0.3
11105837	1002F	< 0.3
11105838	1002G	0.5
11105839	1002H	< 0.3
11105840	10021	< 0.3
11105841	10021	< 0.3
11105842	1002J	< 0.3
11105843	1002K	< 0.3
11113439	1003A	< 0.3
11113440	1003C	< 0.3
11113441	1003D	0.6
11113443	1003D	< 0.3
11113442	1003F	< 0.3
11113444	1003F	< 0.3
11113445	10031	< 0.3
11113446	1003J	< 0.3
11113448	1003J	< 0.3
11113449	1003L	< 0.3
11113450	1003M	0.6
11113451	1003N	< 0.3
11113452	10030	< 0.3
11113453	10030	< 0.3
11113454	10030	< 0.3
11113425	1011A	0.8
11113424	1013A	< 0.3
11113411	1031B	0.6
11113412	1031B	< 0.3
11113413	1031B	< 0.3
11113410	1031C	0.6
11105898	1053A	< 0.3
11105900	1053B	0.6
11105896	1055B	< 0.3
11105847	1070A	< 0.3
11105860	1083A	< 0.3
11105861	1083B	< 0.3
11105865	1083C	0.6
11105866	1083F	< 0.3

Table 1- Radon Testing Results		
	Rockville HS	
Т	est Period: 02/7/2022 - 02/10/2022	
Kit Number	Room / Area	Result
11105868	1084D	0.6
11105869	1084E	< 0.3
11105870	1084F	< 0.3
11105874	1087 DARK ROOM	< 0.3
11105879	1095 OFFICE	1.1
11105885	1101B	0.6
11105886	1101C	0.6
11105855	AUDITORIUM	< 0.3
11105857	AUDITORIUM	0.8

Table 2- Radon Testing Results			
Rockville HS			
	Test Period: 02/7/20	022 - 02/10/2022	
Kit Number	QC Type	Room / Area	Result
11105841	D	10021	< 0.3
11105851	D	1075	< 0.3
11105852	FB	1076	< 0.3
11105862	D	1083	< 0.3
11105872	D	1087	0.6
11105873	FB	1087	< 0.3
11105881	D	1103	< 0.3
11105892	D	1057	0.7
11105893	FB	1057	< 0.3
11113402	D	1001	NA
11113412	D	1031B	< 0.3
11113413	FB	1031B	< 0.3
11113422	D	1013	< 0.3
11113433	D	1022	< 0.3
11113432	FB	1022	< 0.3
11113443	D	1003D	< 0.3
11113454	D	10030	< 0.3
11113453	FB	10030	< 0.3
11113464	D	2017	< 0.3
11113481	ОВ	OFFICE BLANK	< 0.3
11113483	ТВ	TRAVEL BLANK	< 0.3

Summary of Missed Locations		
Rockville HS		
-	Test Period: 02/7/22 - 02/10/22	
Kit Number	Room/Area	Result
	NA	

Summary of Missing, Compromised and >/= 4 piC/L Tests		
Rockville HS		
Test Period: 02/7/22 - 02/10/22		
Kit Number	Room/Area	Result
1113402	1001	Compromised

Table Note:

^{*} Missing or Compromised Sample

ATTACHMENT C

Laboratory Analytical Results

Radon test result report for: ROCKVILLE HS MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11113403	1000	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113405	1000B	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-15
11113404	1000C	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113401	1001	2022-02-07 @ 2:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11113402	1001	2022-02-07 @ 2:00 pm	2022-02-10 @ 2:00 pm	???? IF1	2022-02-14
11105831	1002	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-15
11105832	1002A	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-15
11105833	1002B	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-15
11105834	1002C	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-15
11105836	1002D	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11105835	1002D	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-15
11105837	1002F	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11105838	1002G	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	0.5 ± 0.3	2022-02-14
11105839	1002H	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11105841	1002I	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11105840	1002I	2022-02-07 @ 11:00 am	2022-02-10 @ 4:00 pm	< 0.3	2022-02-15
11105842	1002J	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11105843	1002K	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	< 0.3	2022-02-15
11113438	1003	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113439	1003A	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113440	1003C	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113441	1003D	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	0.6 ± 0.4	2022-02-14
11113443	1003D	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113442	1003F	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113444	1003F	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113445	1003I	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113448	1003J	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113449	1003L	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113450	1003M	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	0.6 ± 0.3	2022-02-15
11113452	1003O	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113453	1003O	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113454	1003O	2022-02-07 @ 3:00 pm	2022-02-10 @ 1:00 pm	< 0.3	2022-02-14
11113437	1005	2022-02-07 @ 3:00 pm	2022-02-10 @ 3:00 pm	0.5 ± 0.3	2022-02-14
11113423	1011	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.6 ± 0.3	2022-02-14
11113425	1011A	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.8 ± 0.3	2022-02-14
11113435	1012	2022-02-07 @ 3:00 pm	2022-02-10 @ 3:00 pm	0.6 ± 0.3	2022-02-14
11113422	1013	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
		•	•		

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for: ROCKVILLE HS MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11113421	1013	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113424	1013A	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113420	1015	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113419	1017	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.8 ± 0.3	2022-02-14
11113418	1019	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113436	1020	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.7 ± 0.3	2022-02-14
11113417	1021	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.6 ± 0.3	2022-02-14
11113431	1022	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.6 ± 0.3	2022-02-14
11113432	1022	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113433	1022	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-15
11113416	1023	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113430	1024	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113415	1025	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.8 ± 0.3	2022-02-14
11113434	1029	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113429	1030	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-15
11113411	1031B	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.6 ± 0.3	2022-02-14
11113412	1031B	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113413	1031B	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113410	1031C	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.6 ± 0.3	2022-02-14
11113428	1032	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-15
11113409	1033	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.7 ± 0.3	2022-02-14
11113408	1035	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.8 ± 0.3	2022-02-14
11113427	1036	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.6 ± 0.3	2022-02-14
11113407	1037	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.6 ± 0.3	2022-02-14
11113426	1038	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.5 ± 0.3	2022-02-14
11113406	1039	2022-02-07 @ 2:00 pm	2022-02-10 @ 3:00 pm	0.8 ± 0.3	2022-02-14
11113455	1049	2022-02-07 @ 3:00 pm	2022-02-10 @ 4:00 pm	0.5 ± 0.3	2022-02-14
11113469	1050	2022-02-07 @ 4:00 pm	2022-02-10 @ 4:00 pm	< 0.3	2022-02-14
11105898	1053A	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105900	1053B	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-14
11105899	1054	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105897	1054	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-14
11105896	1055B	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105891	1057	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105893	1057	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105892	1057	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	0.7 ± 0.3	2022-02-14
11105894	1059	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14

Radon test result report for: ROCKVILLE HS MAIN

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
11105895	1060	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105844	1062	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	1.1 ± 0.4	2022-02-14
11113456	1067	2022-02-07 @ 3:00 pm	2022-02-10 @ 4:00 pm	0.8 ± 0.3	2022-02-14
11105845	1069	2022-02-07 @ 11:00 am	2022-02-10 @ 1:00 pm	0.5 ± 0.3	2022-02-14
11105846	1070	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	0.8 ± 0.3	2022-02-14
11105847	1070A	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105848	1071	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-15
11105849	1073	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	0.7 ± 0.3	2022-02-14
11105850	1075	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105854	1076	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	0.8 ± 0.3	2022-02-14
11105853	1076	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-15
11105852	1076	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	< 0.3	2022-02-15
11105858	1080	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105863	1081	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105862	1083	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-15
11105859	1083	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-15
11105860	1083A	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105861	1083B	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105865	1083C	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-14
11105866	1083F	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-15
11105873	1084	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105867	1084	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105868	1084D	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-14
11105869	1084E	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105870	1084F	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105871	1087	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-14
11105872	1087	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-15
11105874	1087 DARK ROOM	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105875	1089	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105876	1091	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-14
11105877	1093	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.5 ± 0.3	2022-02-14
11105878	1095	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.9 ± 0.3	2022-02-14
11105879	1095 OFFICE	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	1.1 ± 0.3	2022-02-14
11105890	1097	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-14
11105889	1097	2022-02-07 @ 1:00 pm	2022-02-10 @ 2:00 pm	0.7 ± 0.3	2022-02-15
11105882	1101	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105885	1101B	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.4	2022-02-15

Radon test result report for: ROCKVILLE HS MAIN

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
11105886	1101C	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.6 ± 0.3	2022-02-15
11105880	1103	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.7 ± 0.3	2022-02-14
11105881	1103	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105883	1105	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.7 ± 0.3	2022-02-14
11105887	1107	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.9 ± 0.3	2022-02-14
11105888	1109	2022-02-07 @ 12:00 pm	2022-02-10 @ 2:00 pm	0.7 ± 0.3	2022-02-14
11113466	2010	2022-02-07 @ 4:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113465	2014	2022-02-07 @ 4:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-15
11113463	2017	2022-02-07 @ 4:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113462	2017	2022-02-07 @ 4:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-15
11113464	2017	2022-02-07 @ 4:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-15
11113467	2067	2022-02-07 @ 4:00 pm	2022-02-10 @ 3:00 pm	0.5 ± 0.4	2022-02-15
11113461	2071	2022-02-07 @ 4:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-15
11113460	2091	2022-02-07 @ 3:00 pm	2022-02-10 @ 3:00 pm	0.8 ± 0.3	2022-02-14
11113459	2099	2022-02-07 @ 3:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113457	2114	2022-02-07 @ 3:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113458	2115	2022-02-07 @ 3:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11113468	3039	2022-02-07 @ 4:00 pm	2022-02-10 @ 3:00 pm	< 0.3	2022-02-14
11105855	AUDITORIUM	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11105857	AUDITORIUM	2022-02-07 @ 11:00 am	2022-02-10 @ 2:00 pm	0.8 ± 0.3	2022-02-15

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

** LABORATORY ANALYSIS REPORT **

Radon test result report for: ROCKVILLE HS MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11113446	1003J	2022-02-07 @ 9:00 am	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11113451	1003N	2022-02-07 @ 9:00 am	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14
11113414	1027	2022-02-07 @ 10:00 am	2022-02-10 @ 3:00 pm	0.7 ± 0.3	2022-02-14
11105851	1077	2022-02-07 @ 9:00 am	2022-02-10 @ 2:00 pm	< 0.3	2022-02-14

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

EXPOSURE IN BOWSER-MORNER RADON CHAMBER

CLIENT KCI Technologies	Inc. Job Number 204186
	pCi/L Rel. Hum 50.1 % Temp. 70.9
Date Start: <u>a / 18 b-2</u> Date Stop: <u>2/a 1/a</u>	2 Date Start: Date Stop:
Time Start: Q911 Time Stop: Q911	Time Start: Time Stop:
Device No.'s: (3) Char Bog 5-	Device No.'s:
11113484, 11112998, 20107126	
23 Right	
Date Start: Date Stop:	Date Start: Date Stop:
Time Start: Time Stop:	Time Start: Time Stop:
Device No.'s:	Device No.'s:
	×
(C)	
9	
Date Start: Date Stop:	Date Start: Date Stop:
Time Start: Time Stop:	Time Start: Time Stop:
Device No.'s:	Device No.'s:
	3:

Note: All times are in 24-hour (military) notation, Eastern Standard Time (EST) Background = $7 \mu R/h$ Elevation = 820 ft

** LABORATORY ANALYSIS REPORT **

Pg 1 of 1

MCPS - Spike Sample Lab Results. Measured values are satisfactory, i.e., within \pm 25% of the chamber's reference value (25.7 pCi/L).

Kit Number	Start Date	Start Time	End Date	End Time	Temp.	Facility	Building	Room	Project ID	Floor	Result
11113484	2022-02-18	9:00 am	2022-02-21	9:00 am	71	OFFICE	MAIN	SK1		1	27.9
11122998	2022-02-18	9:00 am	2022-02-21	9:00 am	71	OFFICE	MAIN	SK2		1	26.0
20107126	2022-02-18	9:00 am	2022-02-21	9:00 am	71	OFFICE	MAIN	SK3		1	27.6

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498



Engineers • Planners • Scientists • Construction Managers

Corporate Office: 936 Ridgebrook road • Sparks , Maryland 21152 • 410-316-7800 • (Fax) 410-316-7935

Radon Test Kit Chain of Custody

Project Name: MCPS Radon - February 2022 Schools

Name of Schools:

- 1. Lincoln Center
- 2. Wootton HS
- 3. Rockville HS
- 4. Richard Montgomery HS
- 5. Rocking Horse Rd. Center
- 6. Blair G. Ewing Center
- 7. Twinbrook ES
- 8. Rock Creek Valley ES
- 9. Luxmanor ES
- 10.Tilden MS

	Date	Initials
Radon Test Kits Deployed	02/07/2022	n
Radon Test Kits Collected	02/10/2022	7m
Radon Test Kits Shipped to Lab*	02/10/2022	M
Radon Test Kits Received by Lab*	02/14/2022	a

^{*}All samples sent to Air Check, Inc., 1936 Butler Bridge Rd, Mills River, NC 28759

RADON SCREENING SURVEY – FOLLOW-UP ROCKVILLE HIGH SCHOOL

2100 Baltimore Road, Rockville Maryland 20851

EXECUTIVE SUMMARY

Date of Test Report:	4/6/16 Follow-Up
Round of Testing:	Initial
	Follow-up
	Post Remediation
# Rooms Tested	4
# Rooms ≥ 4.0 pCi/L:	0
Low Value:	<0.4
High Value:	0.5
Confirmed Rooms ≥ 4.0 pCi/L US EPA	0
Action Level	

Summary of Sampling Events ≥ 4.0 pCi/L

Room	Result (pCi/L)	Result (pCi/L)	Average Result		
	2/10/16 Initial	4/6/16 Follow-Up	(pCi/L)		
1003L	0.8 Tampered	0.4	0.6		
1080	Missing	0.5	0.5		
2067	Damaged	<0.4	<0.4		
3009	Damaged	0.4	0.4		



936 RIDGEBROOK ROAD • SPARKS, MD 21152 • 410-316-7800 • (FAX) 410-316-7935

MCPS RADON TESTING

Executive Summary: Rockville High School

Date of Test Report:	4/6/2016
Round of Testing:	Initial
	Follow-up
	Post Remediation
# Rooms Tested:	4
# Rooms \geq 4.0 pCi/L:	0
Low Value:	< 0.4
High Value:	0.5

Project Status:

Retesting completed; no further action at this time.

KCI TECHNOLOGIES, INC. WWW.kci.com

Engineers • Planners • Scientists • Construction Managers

936 RIDGEBROOK ROAD • SPARKS, MD 21152 • 410-316-7800 • (FAX) 410-316-7935

April 6, 2016

Mr. Richard Cox Indoor Air Quality Team Leader Montgomery County Public Schools 850 Hungerford Drive Rockville, MD 20850

Re: Radon Testing Services

KCI Job # 12146341.31

Location: Rockville High School

2100 Baltimore Road Rockville, MD 20851

Dear Mr. Cox:

KCI Technologies, Inc. (KCI) is pleased to submit the following report to the Montgomery County Public Schools (MCPS) pursuant to completing a "short-term" 3 day radon test for the Rockville High School, located at 2100 Baltimore Road in Rockville, Maryland 20851 (subject site).

Scope of Services:

KCI conducted radon testing at the subject site to evaluate indoor radon levels relative to the USEPA's recommended action level of 4.0 picocuries per Liter (pCi/L) - the level at which EPA recommends that schools take action to reduce the level. KCI conducted the radon testing in accordance with American Association of Radon Scientists and Technologists (AARST) *Protocol for Conducting Measurements of Radon and Radon Decay Products in Schools and Large Buildings*. A National Radon Safety Board (NRSB) Radon Measurement Specialist (certification #14SS056) supervised the testing. Additional information on radon management and the health effects of radon exposure is available from www.montgomerycountymd.gov/dep/air/radon or www.epa.gov/radon.

KCI visited the site on March 21, 2016 and deployed five (5) activated charcoal (AC) radon test kits. KCI deployed radon test kits in frequently-occupied ground contact rooms, and other areas, (if applicable) in accordance with AARST guidance. A floor plan map of the building with the test locations is included as Attachment A of this report.

As a quality control measure, KCI included duplicate samples, field blanks, lab transit blanks, and office blanks in accordance with AARST recommendations. In addition, KCI submitted six (6) test kits to TCS Industries Inc. as spike samples. The spiked tests were exposed to a known radon concentration by TCS prior to being returned to the laboratory for analysis.

KCI returned to the site on March 24, 2016 to retrieve the radon sampling test kits. KCI shipped all radon tests via overnight delivery to AccuStar Labs for analysis by gamma-ray spectroscopy. Accustar Labs is a NRSB certified analytical laboratory for radon analysis (certification # ARL0007) located at 929 Mount

KCI TECHNOLOGIES, INC. WWW.kci.com

Zion Road, Lebanon, Pennsylvania.

Evaluation of Testing Conditions:

The operating condition that represents the greatest amount of significantly occupied time for this building is; heating active, with outdoor temperature averages $\leq 65^{\circ}$ F.

KCI concludes that the test period reasonably represents normal conditions when the building is significantly occupied. Clear characterization of the radon hazard is most likely to be observed under this normal operating condition. Based on the evaluation of test conditions, this test should reasonably characterize radon hazards.

KCI also conducted observations of field conditions which could affect the results of the test and compiled weather data for the testing period. KCI recorded observations of the following conditions in each room at the time of deployment and collection of the radon test kits:

- Indoor temperature,
- HVAC Operation,
- Dehumidifier operation,
- Humidifier operation,
- Ceiling fan operation, and
- Open windows or doors.

Results:

The results of the radon test analysis indicated the following:

Radon Concentration	Room	Result		
≥4.0 piC/L	none	n/a		
<4.0 piC/L	See Attachment B			

Notes:

D- Duplicate sample

The office blank and lab transit blanks had test results of less than the laboratory detection limit of 0.4 pCi/L. Review of the duplicate sample analysis indicates that adequate laboratory measurement precision was achieved. The Spike sample analysis results indicate the laboratory is operating within statistical control limits.

The sampling locations, field observations, and analytical results are listed on Table 1 (Attachment B). The laboratory analytical results are also attached (Attachment C). Laboratory results and exposure data for the spike samples are also included in Attachment C.

Our professional services have been performed in accordance with customary principles and practices in the field of industrial hygiene and engineering. If you have any questions or comments regarding this report, please feel free to contact me at (410) 316-7800.

KCI TECHNOLOGIES, INC. WWW.kci.com

Employee-Owned Since 1988

Mr. Richard Cox April 6, 2016 Page 4

Sincerely,

James M. Moulsdale

James Makelen

Radon Measurement Specialist

KCI Technologies, Inc.

Attachments: A- Floor Plan with Test Locations

B- Table 1-Radon Test Summary Spreadsheet

C- Laboratory Analytical Results

ATTACHMENT A

Floor Plan With Test Locations

ATTACHMENT B

Radon Test Summary Spreadsheet

Table Notes:

AC- Activated Charcoal

ACI- Air Chek, Inc.

D- Duplicate

FB- Field Blank

KCI- KCI Technologies, Inc.

OB- Office Blank*

PM- Project Manager

QC- Quality Control

*Office blanks were submitted at a rate of 1% for all samples deployed in Phase 11 testing. Office blanks were not submitted under each school individually.

Radon Testing Results					
Rockville High School					
Te	est Period: 03/21/16-03/24/16				
Wit Number					
Kit Number Room / Area Result					
3029124 1080 <0.4					
3029122 2067 <0.4					
3029130	3009	0.4			
3029259 1003L 0.4					

Radon Testing Results					
<u> </u>					
Test Period: 03/21/16-03/24/16					
Kit Number QC Type Result					
D (1080)	0.5				
	Rockville High School Test Period: 03/21/16-03/24/16 QC Type				

ATTACHMENT C

Laboratory Analytical Results



NRPP 10511AL NRSB ARL0007 EPA Method #402-R-92-004 **Charcoal Canister** NRPP Device Code 6048 NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 12146341

KCI Technologies

Rockville HS

936 Ridgebrook Rd Sparks MD 21152 2100 Baltimore Road

Rockville MD 20851

Log Number	Device Number	Test Exposu	re Duration:	Area Tested	Result (pCi/L)
3018367	3029259	03/21/2016 2:00 pm	03/24/2016 12:00 pr	n Unit 1003L First Floor	0.4
3018368	3029124	03/21/2016 2:05 pm	03/24/2016 12:05 pr	n Unit 1080 First Floor	<0.4
3018369	3029123	03/21/2016 2:07 pm	03/24/2016 12:06 pr	n Unit 1080 First Floor	0.5
3018370	3029122	03/21/2016 2:10 pm	03/24/2016 12:10 pr	n Unit 2067 Second Floor	<0.4
3018371	3029130	03/21/2016 2:15 pm	03/24/2016 12:15 pr	n Unit 3009 Third Floor	0.4

Comment: A copy of this report was emailed to tehsin@kci.com.

Distributed by: KCI Technologies, Inc.

Date Received: 03/28/2016 Date Logged: 03/28/2016 Date Analyzed: 03/28/2016 Date Reported: 03/29/2016

Report Reviewed By: Shace Llebushing Report Approved By: Quely D. Kiele

Carolyn D. Koke, President, AccuStar Labs

Disclaimer:

The uncertainty of this radon measurement is ~+/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

RECUSTANT AND STATE AND STREET PROFESSIONAL PROPERTY AND STREET AN

Radon Device Type Open Face Canister

888-480-8812 www.accustarlabs.com

Site Tested:

Send Written Report To: Report Count State/Provinc Email Addres City / Town Address Address Name

Site Tested:		Contact Information:	nation:
Site Name	Lockville H.S.	Contact	Tehsin
Address	2100 Bultimore Rd.	Telephone	410-89
Address			
Sity / Town	Poskville.	Technician	
state/Province P	state/Province Postal Code MD 20851	Cert. Number	
est Country	Montgomery County	Signature	
Project Number 12146341	12146341)	

Tehsin Aurangabadwala	410-891-1726					The last in the contract of the last terms are the contract terms and the contract terms are the contract terms.	
Contact	Telephone		Technician	Cert. Number	Signature	ı	
Site Name Locky, 11c + . S.	N		City/Town Rockville	State/Province Postal Code MD 20851	Test Country Montgomery County	Project Number 12146341	
The state of the s						Proje	
KCI Technologies, Inc	936 Ridgebrook Road	and the second s	Sparks	nce Postal Code MD 21152	ntry Baltimore County	ess tehsin@kci.com	

						_			
Lab Use Only									
Stop Time	12. 8 B	12°50	Been	13-0	(2,5)				
Stop Date	3/24/16				>				
Start Time	30	205.	2007 PM	2 10 mm	2 15 pm				
Start Date	3/21/2016	302/102/12/8	3/21/2014 207	3/21/2016 2 10	3/21/2016			2	
Name of Room	77				→				
Floor	1		~	7	М				
Unit Number	7500)	080)	(080	201e7	3009				
Building Number									
Device Number	3029259	4216208	3029123	3029122	3029(30				
Lab Use Only					194)				

1 of 1



NRPP 10511AI NRSB ARL0007 EPA Method #402-R-92-004 **Charcoal Canister** NRPP Device Code 6048 NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 12146341

KCI Technologies 936 Ridgebrook Rd

Sparks MD 21152

MCPS Radon Phase 11 (re-testing) Office Blank

Device Log Number Number

Test Exposure Duration:

Area Tested

Result (pCi/L)

3018362 3029232 03/21/2016 8:00 am

03/24/2016 8:00 am

Unit O First Floor Main Room

< 0.4

Comment: A copy of this report was emailed to tehsin@kci.com.

Distributed by: KCI Technologies, Inc.

Date Received: 03/28/2016 Date Logged: 03/28/2016 Date Analyzed: 03/28/2016 Date Reported: 03/29/2016

Report Reviewed By: Shace Llegaling Report Approved By: ____ Quoly D. Kiole

Carolyn D. Koke, President, AccuStar Labs

Disclaimer:

The uncertainty of this radon measurement is ~+/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

Accustar Labs
11 And Street
Professional Retor Leboratory Sarriess Since 1984 Medway MA 02053

888-480-8812 www.accustarlabs.com

Radon Device Type Open Face Canister

Site Tested: Send Written Report To:

Test C Site N Addre Addre City / State/ KCI Technologies, Inc 936 Ridgebrook Road State/Province Postal Code MD Report Country Baltimore County Email Address tehsin@kci.com Sparks City / Town Address Address Name

	92	
OFFICE	RICHEBROOK	,
ا ا ا	936	V
Φ		9

Site Name	KCI OFFICE
Address	936 RICHEBROOK RD
Address	
City / Town	SPARIKS
State/Province	State/Province Postal Code MD 721157
Test Country	Montgomery County
Project Number 12146341	12146341
	TO SHADE AND ADDRESS OF THE PARTY OF THE PAR

	Contact Information:	nation:	
FICE	Contact	Tehsin Aurangabadwala	
KEBROOK RD	Telephone	410-891-1726	
MD 21157 County	Technician Cert. Number Signature		

		 ,	 		 	
Lab Use Only						
Stop Time	8:00 Am					
Stop Date	8:00 AM 3/24/2016					
Start Time						
Start Date	72 3/21/20C					
Name of Room Temp	MAIN 72					
Floor	_					
Unit Number	0					
Building Number						
Device Number	3029232					
Lab Use Only						

1 of 1



NRPP 10511AL NRSB ARL0007 EPA Method #402-R-92-004 Charcoal Canister NRPP Device Code 6048 NRSB Device Code 10317

Laboratory Report for:

Property Tested:

KCI Technologies

MCPS

936 Ridgebrook Rd

Transit Blanks

Sparks MD 21152

Log Number	Device Number	Test Exposu	re Duration:	Area Tested	Result (pCi/L)
3010588	3028953	01/19/2016 1:00 pm	01/22/2016 9:30 am	1	< 0.4
3010589	3028955	01/19/2016 1:00 pm	01/22/2016 9:30 am	2	< 0.4
3010590	3028954	01/19/2016 1:00 pm	01/22/2016 9:30 am	3	< 0.4
3010591	3028997	01/19/2016 1:00 pm	01/22/2016 9:30 am	4	< 0.4

Comment: AMENDED REPORT for 3028953-8955, 3028997 on 2/22/16 to add all missing information from the blank datasheet. A copy of this report was emailed to james.moulsdale@kci.com.

Distributed by: KCI Technologies, Inc.

Date Received: 01/27/2016 Date Logged: 01/27/2016 Date Analyzed: 01/28/2016 Date Reported: 01/28/2016

> Report Reviewed By: Cristo Sates Report Approved By: Buly D. Kole Carolyn D. Koke, President, AccuStar Labs

Disclaimer:

The uncertainty of this radon measurement is ~+/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

explain if NO Do not use this form in explain if NO Were general operating New Jersey or Florida conditions maintained? conditions maintained? Yes - No Call for correct forms. Were closed building Multi-Page Report Y-N 0 LAB USE ONLY 1/27/2016 3010588 3028953 ACPC275B EXP12/31/2018 Certilled I coror # # Discrepancies will invalidate tests Normal Temp. Wgt. Gain Yes - No Yes - No Instructions on back of form Read instructions carefully Teros Include AM/PM Stop Time 9130an Both Placed by and Retrieved by signatures are required KCI Technologies, Inc. Date Stop Date 1/22/1 gran. a. Accustar Labs
929 Mt. Zion Rd., Lebanon, PA 17046 RECEIVED JAN 2NFORMATION FORM - Large Buildings Include AM/PM Start Time Canisters retrieved by Owner waives confidentiality ams Email: County Canisters placed by AccuStar Labs - Lebanon, PA Projects - Apartments by signing here Zip Start Date 19/10 91110 1/6/ Attention: Fax: O て Floor State: Zip Structure Type: (circle one or more) Basement - Crawlspace - Slab on Grade - Other Phone: ROOM NAME & NUMBER - LOCATION OF DETECTOR IN - Public School 3010590 Other 3010589 3010588 3010591 State ROOM (indicate duplicates and blanks) Follow Up Test Private Day Care - Private School 1 ransat Residential - Non Residential Day Care in Public School Name of Building/Project or Owner Initial Screening Post Mitigation Trans, t Tack raks, 1 ransit Return canisters for analysis to: Transi rans, 1 Projects Contact Name: 49.3 Company Name: Mc 936 Detector Serial# 410-5 Site Address: **Building Type:** (Circle all that apply) Test Site Info 8955 Test Purpose: 4568 3028953 800-523-4964 200 Send Results To: (Circle One) Address: Phone: City: City:

9

3 6

9

If a recalculation is requested there is a \$10.00 recalc fee PER Canister. Make sure information is complete and correct.

Shipping: 929 Mt Zion Road, Lebanon, PA 17046 Mailing: PO Box 990 Jonestown, PA 17038 800-523-4964 fax 717-274-5662

Cor

i.

0

4 ouls dale

ame

EMAIL Results to:

NEHA 10511AL NRSB ARL 0007

Revision 5 4/2015

Rainy Y-N

Yes - No

Normal Humidity Windy Y-N

TCS INDUSTRIES, INC.

(717) 657-7032

RADON GAS DETECTION

www.radondetek.com

4326 Crestview Road, Harrisburg, PA 17112

James Moulsdale KCI 936 Ridgebrook Rd. Sparks, MD 21152 April 04, 2016

Dear Mr. Moulsdale:

The spike exposure data were:

Start 04/04/16 @ 1110 hrs EDT End 04/06/16 @ 1113 hrs EDT

AC 3029218, 3029219, 3029220, 3029217, 3029214, 3029217, and 3029166

Average radon concentration was 10.6 pCi/L +/- 5%

Avg, Temp. was 71F

Avg. RH was 51%

Elevation was 490 feet above sea level

Sincerely,

Carl H. Distenfeld, CHP

TCS Radon Chamber NRSB CHM 0002



NRPP 10511AL NRSB ARL0007 EPA Method #402-R-92-004 Charcoal Canister NRPP Device Code 6048 NRSB Device Code 10317

Laboratory Report for:

Property Tested:

KCI Technologies

MCPS

936 Ridgebrook Rd

Radon Spike Sample Laboratory Results

Sparks MD 21152

Log Number	Device Number	Test Exposul	re Duration:	Area Tested	Result (pCi/L)
3020102	3029166	04/04/2016 11:10 am	04/06/2016 11:13 a	m Not Indicated	11.9
3020103	3029214	04/04/2016 11:10 am	04/06/2016 11:13 a	m Not Indicated	11.5
3020104	3029217	04/04/2016 11:10 am	04/06/2016 11:13 a	m Not Indicated	10.7
3020105	3029218	04/04/2016 11:10 am	04/06/2016 11:13 a	m Not Indicated	11.3
3020106	3029219	04/04/2016 11:10 am	04/06/2016 11:13 a	m Not Indicated	11.0
3020107	3029220	04/04/2016 11:10 am	04/06/2016 11:13 a	m Not Indicated	10.5

Comment: A copy of this report was emailed to james.moulsdale@kci.com.

Distributed by: KCI Technologies, Inc.

Date Received: 04/07/2016 Date Logged: 04/07/2016 Date Analyzed: 04/07/2016 Date Reported: 04/08/2016

Note: Spike samples are test canisters that are deliberately exposed to a controlled high level of radon in a laboratory. They provide a quality control measure in the testing process and do NOT reflect radon levels in the building being tested.

Report Reviewed By: __

Report Approved By: Bully A Kole

Carolyn D. Koke, President, AccuStar Labs

Disclaimer:

The uncertainty of this radon measurement is ~+/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

Radon Device Type Open Face Canister

888-480-8812 www.accustarlabs.com

Send Written Report To:	Report To:	Site Tested:			Contact Information:	nation:
Name	KCI Technologies, Inc	Site Name	MCPS		Contact	Tehsin Aurangabadwala
Address	936 Ridgebrook Road	Address	840 Hansel d	7	Telephone	410-891-1726
Address		Address				
City / Town	Sparks	City / Town	Patrille		Technician	
State/Province	State/Province Postal Code MD 21152	State/Province F	State/Province Postal Code MD	20850	Cert. Number	
Report Country	Report Country Baltimore County	Test Country	Montgomery County		Signature	i him My
Email Address	Email Address tehsin@kci.com	Project Number 12146341	12146341			MANS
		-				

	.,			- 					,
Lab Use Only									
Stop Time	11:13an	_				->			
Stop Date mm/dd/yyyy	91/9/4)			
Start Time	11:10an					>			
Start Date	91/4/4					\			
Name of Room Temp		2	8	J	5	9			
Floor	1	,)	_	_			
Unit									
Building Number	1		1	1	_	_			
Device Number	3029166	3029214	3029217	3029218	8029219	3029220		-	
Lab Use Only									

1 of 1



936 RIDGEBROOK ROAD • SPARKS, MD 21152 • 410-316-7800 • (FAX) 410-316-7935

MCPS RADON TESTING

Executive Summary: Rockville High School

Date of Test Report:	2/10/2016
Round of Testing:	Initial
	Follow-up
	Post Remediation
# Rooms Tested:	105
# Rooms \geq 4.0 pCi/L:	0
Low Value:	< 0.3
High Value:	2.6

Project Status:

Initial testing completed; missing or compromised samples need re-test.

KCI TECHNOLOGIES, INC. WWW.kci.com

ENGINEERS • PLANNERS • SCIENTISTS • CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD • SPARKS, MD 21152 • 410-316-7800 • (FAX) 410-316-7935

February 10, 2016

Mr. Richard Cox Indoor Air Quality Team Leader Montgomery County Public Schools 850 Hungerford Drive Rockville, MD 20850

Re: Radon Testing Services

KCI Job # 12146341.24

Location: Rockville High School

2100 Baltimore Road Rockville, MD 20851

Dear Mr. Cox:

KCI Technologies, Inc. (KCI) is pleased to submit the following report to the Montgomery County Public Schools (MCPS) pursuant to completing a "short-term" 3 day radon test for the Rockville High School, located at 2100 Baltimore Road in Rockville, Maryland 20851 (subject site).

Scope of Services:

KCI conducted radon testing at the subject site to evaluate indoor radon levels relative to the USEPA's recommended action level of 4.0 picocuries per Liter (pCi/L) - the level at which EPA recommends that schools take action to reduce the level. KCI conducted the radon testing in accordance with American Association of Radon Scientists and Technologists (AARST) *Protocol for Conducting Measurements of Radon and Radon Decay Products in Schools and Large Buildings*. A National Radon Safety Board (NRSB) Radon Measurement Specialist (certification #14SS056) supervised the testing. Additional information on radon management and the health effects of radon exposure is available from www.montgomerycountymd.gov/dep/air/radon or www.epa.gov/radon.

KCI visited the site on January 11, 2016 and deployed one hundred thirty (130) activated charcoal (AC) radon test kits. KCI deployed radon test kits in frequently-occupied ground contact rooms, and other areas, (if applicable) in accordance with AARST guidance. A floor plan map of the building with the test locations is included as Attachment A of this report.

As a quality control measure, KCI included duplicate samples, field blanks, lab transit blanks, and office blanks in accordance with AARST recommendations. In addition, KCI submitted six (6) test kits to Bowser-Morner, Inc. as spike samples. The spiked tests were exposed to a known radon concentration by Bowser-Morner prior to being returned to the laboratory for analysis.

KCI returned to the site on January 14, 2016 to retrieve the radon sampling test kits. KCI shipped all radon tests via overnight delivery to Airchek, Inc. for analysis by gamma-ray spectroscopy. Airchek, Inc. is a NRSB certified analytical laboratory for radon analysis (certification # ARL1402) located at 1936

www.kci.com

Butler Bridge Road, Mills River, North Carolina.

Evaluation of Testing Conditions:

The operating condition that represents the greatest amount of significantly occupied time for this building is; heating active, with outdoor temperature averages $\leq 65^{\circ}$ F.

KCI concludes that the test period reasonably represents normal conditions when the building is significantly occupied. Clear characterization of the radon hazard is most likely to be observed under this normal operating condition. Based on the evaluation of test conditions, this test should reasonably characterize radon hazards.

KCI also conducted observations of field conditions which could affect the results of the test and compiled weather data for the testing period. KCI recorded observations of the following conditions in each room at the time of deployment and collection of the radon test kits:

- Indoor temperature,
- HVAC Operation,
- Dehumidifier operation,
- Humidifier operation,
- Ceiling fan operation, and
- Open windows or doors.

Results:

The results of the radon test analysis indicated the following:

Radon Concentration	Room	Result				
≥4.0 piC/L	none	n/a				
<4.0 piC/L	See Attachment B					

Notes:

D- Duplicate sample

All field blanks, office blank, and lab transit blanks had test results of less than the laboratory detection limit of 0.3 pCi/L. Review of the duplicate sample analysis indicates that adequate laboratory measurement precision was achieved. The Spike sample analysis results indicate the laboratory is operating within statistical control limits.

The sampling locations, field observations, and analytical results are listed on Table 1 (Attachment B). The laboratory analytical results are also attached (Attachment C). Laboratory results and exposure data for the spike samples are also included in Attachment C.

Our professional services have been performed in accordance with customary principles and practices in the field of industrial hygiene and engineering. If you have any questions or comments regarding this report, please feel free to contact me at (410) 316-7800.

Mr. Richard Cox February 10, 2016 Page 4

Sincerely,

H. Allen Bennett

Certified Industrial Hygienist

KCI Technologies, Inc.

H. allen Burnett

Attachments: A- Floor Plan with Test Locations

B- Table 1-Radon Test Summary Spreadsheet

C- Laboratory Analytical Results

ATTACHMENT A

Floor Plan With Test Locations

ATTACHMENT B

Radon Test Summary Spreadsheet

	Radon Testing Results	
	Rockville High School	
	Test Period: 01/11/16-01/14/16	
Kit Number	Room / Area	Result
7721932	1000	< 0.3
7721932	1000	< 0.3
7721916	1000	< 0.3
7721936	1001	0.5
7721914	1002	< 0.3
7721914	1005	0.6
7721984	1011	< 0.3
7721981	1012	0.6
7721988	1013	< 0.3
7721992	1015	< 0.3
7721992	1017	1.3
7721997	1019	0.7
7721996	1020	< 0.3
7721999	1020	< 0.3
7721994	1022	< 0.3
7721986	1023	< 0.3
7721998	1024	< 0.3
7712551	1025	0.6
7712550	1027	< 0.3
7721989	1030	< 0.3
7721990	1032	0.6
7712544	1033	< 0.3
7712541	1035	0.7
7721993	1036	0.7
7712540	1037	< 0.3
7712537	1038	< 0.3
7712535	1039	< 0.3
7721938	1049	< 0.3
7721939	1054	< 0.3
7721941	1054	0.6
7721946	1057	< 0.3
7721950	1059	< 0.3
7721943	1060	< 0.3
7721977	1062	0.9
7721980	1067	0.7
7721979	1069	1
7721972	1070	0.7
7721975	1075	0.8
7721971	1076	0.8
7721964	1076	1.1
7721965	1081	0.9
7721952	1083	2.2
7721959	1084	2.6
7721948	1089	< 0.3
7721961	1093	0.8
7721951	1095	< 0.3

Table Note:
* Missing or Compromised Sample

Radon Testing Results Rockville High School Test Period: 01/11/16-01/14/16					
Kit Number	Room / Area	Result			
7721949	1097	0.6			
7721947	1097	0.7			
7721944	1103	< 0.3			
7721940	1105	0.8			
7721957	1107	1.3			
7721953	1109	1			
7712542	2015	< 0.3			
7712563	2015	< 0.3			
7712538	2027	< 0.3			
7712539	2039	< 0.3			
7712562	2042	0.5			
7712536	2051	0.6			
7712546	2076	< 0.3			
7712570	2101	< 0.3			
7712574	2119	0.6			
7712553	2034	< 0.3			
7712532	3014	< 0.3			
7712554	3019	< 0.3			
7712555	3033	< 0.3			
7721928	1000 B	< 0.3			
7721920	1000 C	< 0.3			
7721902	1002 A	0.8			
7721937	1002 B	< 0.3			
7721934	1002 C	< 0.3			
7721933	1002 D	0.6			
7721921	1002 E	< 0.3			
7721923	1002 F	0.6			
7721919	1002 H	0.7			
7721925	1002	< 0.3			
7721922	1002 J	0.6			
7721929	1002 K	< 0.3			
7721927	1002 L	< 0.3			
7721924	1003 B	< 0.3			
7721909	1003 C	< 0.3			
7721910 7721915	1003 D 1003 H	< 0.3			
		0.6 < 0.3			
7721912 7721904	1003 I	< 0.3			
	1003 J 1003 K				
7721906 7721908	* 1003 K * 1003 L (Tampered)	< 0.3 0.8			
7721917	1003 L (Tampered)	< 0.3			
7721917	1003 M	< 0.3			
7721913	1003 N 1003A	0.7			
7721974	1003A 1011 A	< 0.3			
7721974	1011 A	< 0.3			
7721978	1011 E	< 0.3			
7721976	1011 E	< 0.3			
7721985	1015 C	< 0.3			
7712545	1013 C	< 0.3			
1112040	ם ו 100 ו	` 0.0			

1031 C

< 0.3

7712547

Table Note:
* Missing or Compromised Sample

Radon Testing Results						
	Rockville High School					
	Test Period: 01/11/16-01/14/16					
Kit Number	Room / Area	Result				
7721903	1050 PB	< 0.3				
7721911	1053 A	1				
7721905	1053 B	< 0.3				
7721945	1055B	< 0.3				
7721976	1070 A	< 0.3				
7721960	1076 A	0.7				
7721966	* 1080 (Missing)	0				
7721970	1080 B	1.2				
7721969	1080 D	1.1				
7721967	1080C	1.2				
7721956	1083 F	1.1				
7721955	1095 B	0.7				
7722543	* 2067 (Damaged -Voided by Lab)	0				
7722533	* 3009 (Damaged -Voided by Lab)	0				

	Radon Testing Results				
	Rockville High School				
	Test Period: 01/11/16-01/14/16				
Kit Number	QC Type	Result			
7721901	D (1002)	< 0.3			
7721935	D (1003 N)	< 0.3			
7721991	D (1013)	< 0.3			
7712534	D (1024)	< 0.3			
7712549	D (1031 B)	< 0.3			
7721907	D (1053 A)	1.1			
7721968	D (1070 A)	0.8			
7721963	D (1081)	1.1			
7721954	D (1107)	1			
7712566	D (2042)	0.6			
7712559	D (2076)	< 0.3			
7721930	FB (1002)	< 0.3			
7721916	FB (1003 N)	< 0.3			
7721982	FB (1024)	< 0.3			
7721942	FB (1055 B)	< 0.3			
7721973	FB (1070 A)	< 0.3			
7721958	FB (1107)	< 0.3			
7712558	FB (3019)	< 0.3			
7720174	OB (0)	< 0.3			
7721800	OB (0)	< 0.3			

Table Note:
* Missing or Compromised Sample

Table Notes:

AC- Activated Charcoal

ACI- Air Chek, Inc.

D- Duplicate

FB- Field Blank

KCI- KCI Technologies, Inc.

OB- Office Blank

PM- Project Manager

QC- Quality Control

ATTACHMENT C

Laboratory Analytical Results

Radon test result report for: ROCKVILLE HIGH SCHOOL MAIN

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
7720174	0	2016-01-11 @ 3:00 pm	2016-01-14 @ 12:00 pm	< 0.3	2016-01-18
7721800	0	2016-01-11 @ 3:00 pm	2016-01-14 @ 12:00 pm	< 0.3	2016-01-18
7721918	1000	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721932	1000	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721928	1000 B	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721920	1000 C	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721936	1001	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721901	1002	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721926	1002	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	0.5 ± 0.3	2016-01-18
7721930	1002	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721902	1002 A	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	0.8 ± 0.3	2016-01-18
7721937	1002 B	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721934	1002 C	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721933	1002 D	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	0.6 ± 0.3	2016-01-18
7721921	1002 E	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721923	1002 F	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	0.6 ± 0.3	2016-01-18
7721919	1002 H	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	0.7 ± 0.3	2016-01-18
7721925	1002 I	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721922	1002 J	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	0.6 ± 0.3	2016-01-18
7721929	1002 K	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721927	1002 L	2016-01-11 @ 9:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721914	1003	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721924	1003 B	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721909	1003 C	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721910	1003 D	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721915	1003 H	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	0.6 ± 0.3	2016-01-18
7721912	1003 I	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721904	1003 J	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721906	1003 K	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721908	1003 L	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	0.8 ± 0.3	2016-01-18
7721917	1003 M	2016-01-11 @ 10:00 am	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721913	1003 N	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721916	1003 N	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721935	1003 N	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721931	1003A	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	0.7 ± 0.3	2016-01-18
7721983	1005	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.6 ± 0.3	2016-01-18
7721984	1011	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18

Radon test result report for: ROCKVILLE HIGH SCHOOL MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7721974	1011 A	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721987	1011 D	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721978	1011 E	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721981	1012	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.6 ± 0.3	2016-01-18
7721988	1013	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721991	1013	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721985	1013 D	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721992	1015	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721995	1015 C	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7722000	1017	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	1.3 ± 0.3	2016-01-18
7721997	1019	2016-01-11 @ 1:00 pm	2016-01-14 @ 10:00 am	0.7 ± 0.3	2016-01-18
7721996	1020	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721999	1021	2016-01-11 @ 1:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721994	1022	2016-01-11 @ 1:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721986	1023	2016-01-11 @ 1:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7712534	1024	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7721982	1024	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7721998	1024	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712551	1025	2016-01-11 @ 2:00 pm	2016-01-14 @ 10:00 am	0.6 ± 0.3	2016-01-18
7712550	1027	2016-01-11 @ 2:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721989	1030	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712545	1031 B	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712549	1031 B	2016-01-11 @ 2:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7712547	1031 C	2016-01-11 @ 2:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721990	1032	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	0.6 ± 0.3	2016-01-18
7712544	1033	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712541	1035	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	0.7 ± 0.3	2016-01-18
7721993	1036	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	0.7 ± 0.3	2016-01-18
7712540	1037	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712537	1038	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712535	1039	2016-01-11 @ 1:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7721938	1049	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721903	1050 PB	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721907	1053 A	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	1.1 ± 0.3	2016-01-18
7721911	1053 A	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	1.0 ± 0.3	2016-01-18
7721905	1053 B	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721939	1054	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18

Radon test result report for: ROCKVILLE HIGH SCHOOL MAIN

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
7721941	1054	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	0.6 ± 0.3	2016-01-18
7721942	1055 B	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721945	1055B	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721946	1057	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721950	1059	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721943	1060	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721977	1062	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.9 ± 0.3	2016-01-18
7721980	1067	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.7 ± 0.3	2016-01-18
7721979	1069	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	1.0 ± 0.3	2016-01-18
7721972	1070	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.7 ± 0.3	2016-01-18
7721968	1070 A	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.8 ± 0.3	2016-01-18
7721973	1070 A	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721976	1070 A	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721975	1075	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.8 ± 0.3	2016-01-18
7721964	1076	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	1.1 ± 0.3	2016-01-18
7721971	1076	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.8 ± 0.3	2016-01-18
7721960	1076 A	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	0.7 ± 0.3	2016-01-18
7721966	1080	@	@		
7721970	1080 B	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	1.2 ± 0.3	2016-01-18
7721969	1080 D	2016-01-11 @ 12:00 pm	2016-01-14 @ 10:00 am	1.1 ± 0.3	2016-01-18
7721967	1080C	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	1.2 ± 0.3	2016-01-18
7721963	1081	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	1.1 ± 0.3	2016-01-18
7721965	1081	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	0.9 ± 0.3	2016-01-18
7721952	1083	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	2.2 ± 0.4	2016-01-18
7721956	1083 F	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	1.1 ± 0.3	2016-01-18
7721959	1084	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	2.6 ± 0.4	2016-01-18
7721948	1089	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721961	1093	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	0.8 ± 0.3	2016-01-18
7721951	1095	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	< 0.3	2016-01-18
7721955	1095 B	2016-01-11 @ 11:00 am	2016-01-14 @ 10:00 am	0.7 ± 0.3	2016-01-18
7721947	1097	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	0.7 ± 0.3	2016-01-18
7721949	1097	2016-01-11 @ 10:00 am	2016-01-14 @ 9:00 am	0.6 ± 0.3	2016-01-18
7721944	1103	2016-01-11 @ 11:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18
7721940	1105	2016-01-11 @ 11:00 am	2016-01-14 @ 9:00 am	0.8 ± 0.3	2016-01-18
7721954	1107	2016-01-11 @ 11:00 am	2016-01-14 @ 9:00 am	1.0 ± 0.3	2016-01-18
7721957	1107	2016-01-11 @ 11:00 am	2016-01-14 @ 9:00 am	1.3 ± 0.3	2016-01-18
7721958	1107	2016-01-11 @ 11:00 am	2016-01-14 @ 9:00 am	< 0.3	2016-01-18

February LABORATORY ANALYSIS 10, REPORT **

Radon test result report for:
ROCKVILLE HIGH SCHOOL
MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7721953	1109	2016-01-11 @ 11:00 am	2016-01-14 @ 9:00 am	1.0 ± 0.3	2016-01-18
7712542	2015	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712563	2015	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712538	2027	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712539	2039	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712566	2042	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	0.6 ± 0.3	2016-01-18
7712562	2042	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	0.5 ± 0.3	2016-01-18
7712536	2051	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	0.6 ± 0.3	2016-01-18
7722543	2067	2016-01-11 @ 1:00 pm	2016-01-14 @ 10:00 am	???? EI	2016-01-26
7712546	2076	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712559	2076	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712570	2101	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712574	2119	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	0.6 ± 0.3	2016-01-18
7712553	2034	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7722533	3009	2016-01-11 @ 1:00 pm	2016-01-14 @ 10:00 am	???? EI	2016-01-27
7712532	3014	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712554	3019	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712558	3019	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18
7712555	3033	2016-01-11 @ 2:00 pm	2016-01-14 @ 11:00 am	< 0.3	2016-01-18

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

February LABORATORY ANALYSIS 2, REPORT **

Radon test result report for: MCPS PHASE 5 & 6 TRANSIT BLANKS

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
7722194	1	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718494	10	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718475	11	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718495	12	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718496	13	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718497	14	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718498	15	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718499	16	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718500	17	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718296	18	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718295	19	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7722195	2	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7716789	20	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7716785	21	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-26
7716791	22	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7716786	23	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7716793	24	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718274	25	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7716792	26	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718294	27	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718293	28	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718292	29	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7722197	3	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718290	30	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7722198	4	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7722199	5	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7722211	6	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718491	7	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27
7718476	8	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-26
7718479	9	2016-01-19 @ 12:00 pm	2016-01-22 @ 12:00 pm	< 0.3	2016-01-27

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

December LABORATORY ANALYSIS 23, REPORT **

Spike Sample Laboratory Results

Radon test result report for: MCPS

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7706380	101	2015-12-18 @ 9:00 am	2015-12-21 @ 9:00 am	25.2	2015-12-23
7706381	102	2015-12-18 @ 9:00 am	2015-12-21 @ 9:00 am	26.5	2015-12-23
7706208	103	2015-12-18 @ 9:00 am	2015-12-21 @ 9:00 am	27.7	2015-12-23
7705132	104	2015-12-18 @ 9:00 am	2015-12-21 @ 9:00 am	28.6	2015-12-23
7706366	105	2015-12-18 @ 9:00 am	2015-12-21 @ 9:00 am	26.5	2015-12-23
7706211	106	2015-12-18 @ 9:00 am	2015-12-21 @ 9:00 am	26.1	2015-12-23

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Note: Spike samples are test canisters that are deliberately exposed to a controlled high level of radon in a laboratory. They provide a quality control measure in the testing process and do NOT reflect radon levels in the building being tested.

EXPOSURE IN BOWSER-MORNER RADON CHAMBER

CLIENT KCI Technologies.	Inc. Job Number 173224
	pCi/L Rel. Hum <u>49.6</u> % Temp. <u>69.9</u>
Date Start: 12/18/15 Date Stop: 12/21/5	Date Start: Date Stop:
Time Start: <u>0929</u> Time Stop: <u>0929</u>	Time Start: Time Stop:
Device No.'s: 7705132,7766208	Device No.'s:
7706211,7706366,	
7706380, 7706381	
F3 Loft	
Date Start: Date Stop:	Date Start: Date Stop:
Time Start: Time Stop:	Time Start: Time Stop:
Device No.'s:	Device No.'s:
	-
1	
Date Start: Date Stop:	Date Start: Date Stop:
Time Start: Time Stop:	Time Start: Time Stop:
Device No.'s:	Device No.'s:

Note: All times are in 24-hour (military) notation, Eastern Standard Time (EST) Background = $7 \mu R/h$ Elevation = 820 ft



Engineers • Planners • Scientists • Construction Managers

Corporate Office: 936 Ridgebrook road • Sparks , Maryland 21152 • 410-316-7800 • (Fax) 410-316-7935

Chain of Custody

Project Name: MCPS Radon Phase V

Name of Schools:

1.	Arcola ES	11. Clopper Mill ES	21. Parkland Magnet MS
2.	Argyle ES	12. College Gardens ES	22. Rachel Carson ES
3.	Bells Mill ES	13. Eastern MS	23. Roberto Clemente MS
4.	Bethesda ES	14. Fallsmead ES	24. Rock Creek ES
5.	Brookhaven ES	15. Fields Road ES	25. Rockview ES
6.	Burning Tree ES	16. Flower Hill ES	26. Rockville HS
7.	Capt. James Daly ES	17. Flower Valley ES	27. Rocky Hill MS
8.	Carderock Springs ES	18. Fox Chapel ES	28. Seneca Valley HS
9.	Cashell ES	19. Glen Haven ES	29. Westover ES
10.	Clearspring ES	20. James Hubert Blake HS	30. William Farquar MS

	Date	Initials
Radon Test Kits Deployed	1/11/16	VM
Radon Test Kits Sampled	1/14/16	JM
Radon Test Kits Shipped to Lab*	1/15/16	JM
Radon Test Kits Received by Lab*	1/18/16	JM

^{*}All samples sent to Air Check, Inc., 1936 Butler Bridge Road, Mills River, NC 28758