COPIER OPERATIONS TIP OF THE MONTH MARCH 2019

HEAT CODES

Partners,

When you are making copies and the codes SC 541 or SC 542 display on your monitor, the copier will shut down. Do not try and search for the problem. These are heat codes, that will require the attention of a technician. Place a service call ASAP.

Remember I am only a phone call away and you can contact me on Outlook (Peter_D_Patellis@mcpsmd.org) for everything you need for your copier.

Pete Patellis Customer Service Specialist TeamWorks Central Montgomery County Public Schools 301-279-3110