

Montgomery County Public Schools Lead in Drinking Water Testing Report

Wheaton High School
12401 Dalewood Dr
Silver Spring, 20906

Report Date: January 25, 2026

LEAD IN DRINKING WATER SAMPLE RESULTS SUMMARY

All Maryland public and nonpublic schools are required to sample all drinking water outlets for the presence of lead pursuant to the Code of Maryland Regulations (COMAR). Montgomery County Public Schools (MCPS) is required to remediate outlets where lead in drinking water concentrations exceed the State Action Level (AL) of 5 parts per billion (ppb). A summary of the lead in water initial samples collected by Environmental Consulting Services, LLC is presented in the table below.

Sampling Date	12/11/2025
# of Outlets Tested	56
# of Outlets \geq 5 ppb	1

NEXT STEPS

If an initial sample exceeds the AL (5 ppb), the outlet will be shut-down within 24 hours, a follow-up sample collected, and a remedial plan of action developed for this outlet. No additional sampling or remedial actions are required for schools where all initial samples are below the AL.

HEALTH EFFECTS OF LEAD

Lead can cause serious health problems if too much enters your body from drinking water or other sources. It can cause damage to the brain and kidneys, and can interfere with the production of red blood cells that carry oxygen to all parts of your body. The greatest risk of lead exposure is to infants, young children, and pregnant women. Lead is stored in the bones and it can be released later in life. During pregnancy, the fetus receives lead from the mother's bones, which may affect brain development. Scientists have linked the effects of lead on the brain with lowered IQ in children. Adults with kidney problems and high blood pressure can be affected by low levels of lead more than healthy adults.

SOURCES OF HUMAN EXPOSURE TO LEAD

There are many different sources of human exposure to lead. These include: lead-based paint, lead-contaminated dust or soil, some plumbing materials, certain types of pottery, pewter, brass outlets, food, cosmetics, exposure in the work place and from certain hobbies. According to the Environmental Protection Agency (EPA), 10 to 20 percent of a person's potential exposure to lead may come from drinking water, while for an infant consuming formula mixed with lead-containing water this may increase to 40 to 60 percent.

TO REDUCE EXPOSURE TO LEAD IN DRINKING WATER:

1. Run your water to flush out lead: If water hasn't been used for several hours, run water for 15 to 30 seconds or until it becomes cold or reaches a steady temperature before using it for drinking or cooking.
2. Use cold water for cooking and preparing baby formula: Lead from the plumbing dissolves more easily into hot water.

**Please note that boiling the water will not reduce lead levels.*

ADDITIONAL INFORMATION

1. For additional information, please contact Brian Mullikin, Environmental Team Leader, at 240.740.2324 or brian_a_mullikin@mcpsmd.org.
2. For additional information on reducing lead exposure around your home/building and the health effects of lead, visit EPA's website at www.epa.gov/lead.
3. If you are concerned about exposure; contact your local health department or healthcare provider to find out how you can get your child tested for lead.

Please refer to the attachment(s) for additional water sampling information.

Attachment(s):

A - Lead in Water Sample Results Table

ATTACHMENT A

Lead in Water Sample Results Table

Sampling Results-Wheaton High School					
Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
LW02602	In hallway next to 1400 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW02785	In hallway 3200 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW05510	In cafeteria hallway	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete
LW05511	In hallway near 1605	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete
LW05512	In hallway near 1712	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete
LW05513	In hallway next to 2026	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete
LW05514	In hallway next to 2200	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete
LW05515	In hallway next to 3200	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete
LW08333	In hallway next to 2306(Left)	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW08334	In hallway next to 2306	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW111819	In hallway next to 3420(Right)	Bottle Filler/Drinking Fountain Combo Unit - Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW111820	In hallway next to 3420	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW111821	In hallway next to 3310(Left)	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW111822	In hallway next to 3310(Right)	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW11823	Next to 3020	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete

Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
LW11824	Left sink in concession stand	Faucet, Cold	<1.0	Pass	Testing Complete
LW11825	Ice machine in concession stand	Ice Machine (Stand Alone)	<1.0	Pass	Testing Complete
LW11826	Right sink in concession stand	Faucet, Cold	4.7	Pass	Testing Complete
M33111	In hallway 1605 across from 1605 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33112	In hallway across from 1605 LTR 2 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33120	In hallway 1712 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33121	In hallway 1712 LTR 2 of 2	Bottle Filler/Drinking Fountain Combo Unit - Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33126	In child development 1716	Faucet, Cold	<1.0	Pass	Testing Complete
M33131	In work room 1000G by administration	Faucet, Cold	2.9	Pass	Testing Complete
M33141	In hallway 1110 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33142	In hallway 1110 LTR 2 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33145	In health room 1115	Faucet, Cold	<1.0	Pass	Testing Complete
M33168	In hallway 1400 LTR 2 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33179	In kitchen 1504 LTR 6 of 6	Faucet, Cold	<1.0	Pass	Testing Complete
M33180	In kitchen 1504 LTR 1 of 2	Multiple Compartment Sink - Faucet, Cold	<1.0	Pass	Testing Complete

Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
M33181	In kitchen 1504 LTR 2 of 2	Multiple Compartment Sink - Faucet, Cold	<1.0	Pass	Testing Complete
M33182	In kitchen 1504 LTR 5 of 6	Faucet, Cold	<1.0	Pass	Testing Complete
M33183	In kitchen 1504	Multiple Compartment Sink - Faucet, Cold	<1.0	Pass	Testing Complete
M33184	In kitchen 1504 LTR 3 of 6	Faucet, Cold	<1.0	Pass	Testing Complete
M33186	In kitchen 1504 LTR 4 of 6	Faucet, Cold	1.6	Pass	Testing Complete
M33187	In kitchen 1504 LTR 2 of 6	Faucet, Cold	<1.0	Pass	Testing Complete
M33188	In kitchen 1504 LTR 1 of 6	Faucet, Cold	<1.0	Pass	Testing Complete
M33190	In cafeteria 1500	Bottle Filler/Drinking Fountain Combo Unit - Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33191	In cafeteria 1500	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33192	In break room 1009	Faucet, Cold	<1.0	Pass	Testing Complete
M33197	In hallway 1315 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33198	In hallway 1315 LTR 2 of 2 (lower)	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33201	In hallway next to 2702 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33202	In hallway next to 2702 LTR 2 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33214	In hallway outside 2026 LTR 2 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete

Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
M33215	In hallway outside 2026 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33226	In hallway adjacent to 2200 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33227	In hallway adjacent to 2200 LTR 2 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33239	In hallway adjacent to 3019 LTR 2 of 2	Bottle Filler/Drinking Fountain Combo Unit - Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33251	In hallway across from 3200 LTR 1 of 2	Bottle Filler/Drinking Fountain Combo Unit - Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33257	In health room 1117E	Faucet, Cold	5.6	Fail	Remediation Action Plan
M33259	In room 1117L	Faucet, Cold	2.5	Pass	Testing Complete
M33260	In health room 1117N	Faucet, Cold	2.4	Pass	Testing Complete
M33263	In health room 1117R	Faucet, Cold	2.4	Pass	Testing Complete
M33267	In hallway adjacent to 2709 LTR 1 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
M33268	In hallway adjacent to 2709 LTR 2 of 2	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete

Montgomery County Public Schools Lead in Drinking Water Testing Report

**Wheaton High School
12401 Dalewood Drive
Silver Spring, MD 20906**

Report Date: June 22, 2023

LEAD IN DRINKING WATER SAMPLE RESULTS SUMMARY

All Maryland public and nonpublic schools are required to sample all drinking water outlets for the presence of lead pursuant to the Code of Maryland Regulations (COMAR). Montgomery County Public Schools (MCPS) is required to remediate outlets where lead in drinking water concentrations exceed the State Action Level (AL) of 5 parts per billion (ppb). A summary of the lead in water initial samples collected by Inspection Experts Inc is presented in the table below.

Sampling Date	3/17/23
# of Outlets Tested	56
# of Outlets \geq 5 ppb	0

NEXT STEPS

If an initial sample exceeds the AL (5 ppb), the outlet will be shut-down within 24 hours, a follow up sample collected, and a remedial plan of action developed for this outlet. No additional sampling or remedial actions are required for schools where all initial samples are below the AL.

HEALTH EFFECTS OF LEAD

Lead can cause serious health problems if too much enters your body from drinking water or other sources. It can cause damage to the brain and kidneys, and can interfere with the production of red blood cells that carry oxygen to all parts of your body. The greatest risk of lead exposure is to infants, young children, and pregnant women. Lead is stored in the bones and it can be released later in life. During pregnancy, the fetus receives lead from the mother's bones, which may affect brain development. Scientists have linked the effects of lead on the brain with lowered IQ in children. Adults with kidney problems and high blood pressure can be affected by low levels of lead more than healthy adults.

SOURCES OF HUMAN EXPOSURE TO LEAD

There are many different sources of human exposure to lead. These include: lead-based paint, lead-contaminated dust or soil, some plumbing materials, certain types of pottery, pewter, brass outlets, food, cosmetics, exposure in the workplace and from certain hobbies. According to the Environmental Protection Agency (EPA), 10 to 20 percent of a person's potential exposure to lead may come from drinking water, while for an infant consuming formula mixed with lead containing water this may increase to 40 to 60 percent.

TO REDUCE EXPOSURE TO LEAD IN DRINKING WATER:

1. Run your water to flush out lead: If water hasn't been used for several hours, run water for 15 to 30 seconds or until it becomes cold or reaches a steady temperature before using it for drinking or cooking.
2. Use cold water for cooking and preparing baby formula: Lead from the plumbing dissolves more easily into hot water.

**Please note that boiling the water will not reduce lead levels.*

ADDITIONAL INFORMATION

1. For additional information, please contact Brian Mullikin, Environmental Team Leader, at 240.740.2324 or brian_a_mullikin@mcpsmd.org.
2. For additional information on reducing lead exposure around your home/building and the health effects of lead, visit EPA's website at www.epa.gov/lead.
3. If you are concerned about exposure; contact your local health department or healthcare provider to find out how you can get your child tested for lead.

Please refer to the attachment(s) for additional water sampling information.

Attachment(s):

A - Lead in Water Sample Results Table

ATTACHMENT A

Lead in Water Sample Results Table

Sampling Results for Wheaton HS

Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
LW02602	In hallway next to 1400	Drinking Fountain	<1.0	Pass	Testing Complete
LW02785	In hallway 3200	Drinking Fountain	<1.0	Pass	Testing Complete
M33111	In hallway 1605	Drinking Fountain	<1.0	Pass	Testing Complete
M33112	In hallway across from 1605	Drinking Fountain	<1.0	Pass	Testing Complete
M33120	In hallway 1712	Drinking Fountain	<1.0	Pass	Testing Complete
M33121	In hallway 1712	Drinking Fountain	<1.0	Pass	Testing Complete
M33126	In child development 1716	Drinking Fountain	<1.0	Pass	Testing Complete
M33131	In work room 1000G by administration	Teachers Lounge Sink	<1.0	Pass	Testing Complete
M33141	In hallway 1110 outside	Drinking Fountain	<1.0	Pass	Testing Complete
M33142	In hallway 1110 outside	Drinking Fountain	<1.0	Pass	Testing Complete
M33145	In health room 1115	Nurses Office Sink	<1.0	Pass	Testing Complete
M33168	In hallway 1400	Drinking Fountain	<1.0	Pass	Testing Complete
M33179	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete
M33180	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete
M33181	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete

Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
M33182	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete
M33183	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete
M33184	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete
M33186	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete
M33187	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete
M33188	In kitchen 1504 by cafeteria	Kitchen Sink	<1.0	Pass	Testing Complete
M33190	In cafeteria 1500 outside of 1600	Drinking Fountain	<1.0	Pass	Testing Complete
M33191	In cafeteria 1500 outside of 1600	Drinking Fountain	<1.0	Pass	Testing Complete
M33192	In break room 1009	Teachers Lounge Sink	<1.0	Pass	Testing Complete
M33197	In hallway 1315	Drinking Fountain	<1.0	Pass	Testing Complete
M33198	In hallway 1315	Drinking Fountain	<1.0	Pass	Testing Complete
M33201	In hallway next to 2702	Drinking Fountain	<1.0	Pass	Testing Complete
M33202	In hallway next to 2702	Drinking Fountain	<1.0	Pass	Testing Complete
M33214	In hallway outside 2026	Drinking Fountain	<1.0	Pass	Testing Complete
M33215	In hallway outside 2026	Drinking Fountain	<1.0	Pass	Testing Complete
M33226	In hallway adjacent to 2200	Drinking Fountain	<1.0	Pass	Testing Complete

Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
M33227	In hallway adjacent to 2200	Drinking Fountain	<1.0	Pass	Testing Complete
M33239	In hallway adjacent to 3019	Drinking Fountain	<1.0	Pass	Testing Complete
M33251	In hallway across from 3200	Drinking Fountain	<1.0	Pass	Testing Complete
M33267	In hallway adjacent to 2709	Drinking Fountain	<1.0	Pass	Testing Complete
M33268	In hallway adjacent to 2709	Drinking Fountain	<1.0	Pass	Testing Complete
M33259	RM 1117L	Nurses Office Sink	<1.0	Pass	Testing Complete
M33263	Health Room 1117R	Nurses Office Sink	<1.0	Pass	Testing Complete
M33257	Health Room 1117E	Nurses Office Sink	<1.0	Pass	Testing Complete
M33263	Health Room 1117P	Nurses Office Sink	<1.0	Pass	Testing Complete
LW111823	HWF-Next 3019 (Left fountain)	Drinking Fountain	<1.0	Pass	Testing Complete
LW05510	HWF-Cafeteria (Bottle filler)	Drinking Fountain	<1.0	Pass	Testing Complete
LW11825	ICE Machine in Concession Stand	Ice Machine	<1.0	Pass	Testing Complete
LW11826	Right Sink in Concession Stand	Faucet,Cold	4.7	Pass	Testing Complete
LW111819	HWF next 3420 (Right)	Drinking Fountain	<1.0	Pass	Testing Complete
LW11824	Left Sink in Concession Stand	Faucet,Cold	<1.0	Pass	Testing Complete
LW11822	HWF Next 3410	Drinking Fountain	<1.0	Pass	Testing Complete

Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
LW05512	HWF-near 1712 (Bottle Filler)	Drinking Fountain	<1.0	Pass	Testing Complete
LW05513	HWF-next-2026 (Bottle Filler)	Drinking Fountain	<1.0	Pass	Testing Complete
LW111820	HWF-next-3420	Drinking Fountain	<1.0	Pass	Testing Complete
LW05511	HWF-next-1605 (Bottle Filler)	Drinking Fountain	<1.0	Pass	Testing Complete
LW111821	HWF-next-3410	Drinking Fountain	<1.0	Pass	Testing Complete
M33260	Health Room 1117N	Nurses Office Sink	4.6	Pass	Testing Complete
LW05515	HWF-next-3200 (Bottle Filler)	Drinking Fountain	<1.0	Pass	Testing Complete
LW05514	HWF-next 2200	Drinking Fountain	<1.0	Pass	Testing Complete
LW05516	HWF-next-3019 (Bottle Filler)	Drinking Fountain	<1.0	Pass	Testing Complete

Montgomery County Public Schools Lead in Drinking Water Testing Report

Wheaton High School
12401 Dalewood Dr
Silver Spring, MD 20906

Report Date: February 18th, 2020

LEAD IN DRINKING WATER SAMPLE RESULTS SUMMARY

All Maryland public and nonpublic schools are required to sample all drinking water outlets for the presence of lead pursuant to the Code of Maryland Regulations (COMAR). Montgomery County Public Schools (MCPS) is required to remediate outlets where lead in drinking water concentrations exceed the Montgomery County Action Level (AL) of 5 parts per billion (ppb). A summary of the lead in water initial samples collected by SaLUT are presented in the table below.

Sampling Date	2/5/2020
# of Outlets Tested	39
# of Outlets \geq 5 ppb	0

NEXT STEPS

If an initial sample exceeds the AL (5 ppb), the outlet will be immediately shut-down, a follow-up sample collected, and a remedial plan of action developed for this outlet. No additional sampling or remedial actions are required for schools where all initial samples are below the AL.

HEALTH EFFECTS OF LEAD

Lead can cause serious health problems if too much enters your body from drinking water or other sources. It can cause damage to the brain and kidneys, and can interfere with the production of red blood cells that carry oxygen to all parts of your body. The greatest risk of lead exposure is to infants, young children, and pregnant women. Lead is stored in the bones and it can be released later in life. During pregnancy, the fetus receives lead from the mother's bones, which may affect brain development. Scientists have linked the effects of lead on the brain with lowered IQ in children. Adults with kidney problems and high blood pressure can be affected by low levels of lead more than healthy adults.

SOURCES OF HUMAN EXPOSURE TO LEAD

There are many different sources of human exposure to lead. These include: lead-based paint, lead-contaminated dust or soil, some plumbing materials, certain types of pottery, pewter, brass fixtures, food, cosmetics, exposure in the work place and from certain hobbies. According to the Environmental Protection Agency (EPA), 10 to 20 percent of a person's potential exposure to lead may come from drinking water, while for an infant consuming formula mixed with lead-containing water this may increase to 40 to 60 percent.

TO REDUCE EXPOSURE TO LEAD IN DRINKING WATER:

1. Run your water to flush out lead: If water hasn't been used for several hours, run water for 15 to 30 seconds or until it becomes cold or reaches a steady temperature before using it for drinking or cooking.
2. Use cold water for cooking and preparing baby formula: Lead from the plumbing dissolves more easily into hot water.

**Please note that boiling the water will not reduce lead levels.*

ADDITIONAL INFORMATION

1. For additional information, please contact Brian Mullikin, Environmental Team Leader, at 240.740.2324 or brian_a_mullikin@mcpsmd.org.
2. For additional information on reducing lead exposure around your home/building and the health effects of lead, visit EPA's website at www.epa.gov/lead.
3. If you are concerned about exposure; contact your local health department or healthcare provider to find out how you can get your child tested for lead.

Please refer to the attachment(s) for additional water sampling information.

Attachment(s) A – Lead in Water Sample Results Table

ATTACHMENT A

Lead in Water Sample Results Table

Sampling Results for Wheaton HS

Fixture Barode	Fixture Location	Fixture Type	Initial Results (ppb)	Pass/Fail	Follow up Results (ppb)	Status
LW02602	In hallway next to 1400	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW02785	In hallway 3200 across from	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW08333	2nd floor hallway next to 2306 (building services)	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW08334	2nd floor	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33111	In hallway 1605 across from 1605	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33112	In hallway across from 1605	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33120	In hallway 1712 outside of	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33121	In hallway 1712 outside of	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33126	In child development 1716	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33131	In work room 1000G by administration	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete
M33141	In hallway 1110 outside	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33142	In hallway 1110 outside	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33145	In health room 1115	Nurses Office Sink	<1	Pass	N/A	Testing Complete
M33168	In hallway 1400 next to	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33179	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33180	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33181	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33182	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33183	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33184	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33186	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33187	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33188	In kitchen 1504 by cafeteria	Kitchen Sink	<1	Pass	N/A	Testing Complete
M33189	In kitchen 1504 by cafeteria ie. across from 1504a	Ice Machine	<1	Pass	N/A	Testing Complete

M33190	In cafeteria 1500 by cafeteria ie. outside of 1600	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33191	In cafeteria 1500 by cafeteria ie. outside of 1600	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33192	In break room 1009	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete
M33197	In hallway 1315 across from	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33198	In hallway 1315 across from	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33201	In hallway next to 2702	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33202	In hallway next to 2702	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33214	In hallway outside 2026	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33215	In hallway outside 2026	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33226	In hallway adjacent to 2200	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33227	In hallway adjacent to 2200	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33239	In hallway adjacent to 3019	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33251	In hallway across from 3200	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33267	In hallway adjacent to 2709	Drinking Fountain	<1	Pass	N/A	Testing Complete
M33268	In hallway adjacent to 2709	Drinking Fountain	<1	Pass	N/A	Testing Complete



Montgomery County Public Schools Lead in Drinking Water Testing 2018

Executive Summary:

Wheaton HS

12401 Dalewood Drive

Silver Spring, Maryland 20906

Date of Test Report:	3/23/2018
Round of Testing:	Initial
# of Outlets Tested:	36
# of Outlets ≥ 20 ppb:	0
Low Value (ppb):	<1.0
High Value (ppb):	<1.0

Project Status:

Initial testing complete: All results less than 20 ppb.



3/23/2018

Mr. Brian Mullikin, MS
Environmental Team Leader
Montgomery County Public Schools
Division of Maintenance
Gaithersburg, Maryland 20879

Re: Drinking Water Testing

KCI Job #1214634186

Location: Wheaton HS
12401 Dalewood Drive
Silver Spring, Maryland 20906

Dear Mr. Mullikin:

KCI Technologies, Inc. (KCI) is pleased to submit the following report to the Montgomery County Public Schools (MCPS) for completion of Initial lead in water testing at Wheaton HS, located at 12401 Dalewood Drive in Silver Spring, Maryland 20906.

SCOPE OF SERVICES

KCI conducted lead in water testing at Wheaton HS in accordance with the Environmental Protection Agency (EPA) and Maryland House Bill (HB) 270. State regulation established an action level of 20 parts per billion (ppb) to evaluate lead levels in school buildings, a concentration EPA recommends that schools take action to reduce lead below this action level. Maryland requires periodic testing for the presence of lead in drinking water in occupied public and nonpublic school buildings. EPA developed the 3T's (Training, Testing, and Telling) to assist schools in reducing the lead concentrations in their drinking water. More information about 3T's can be found on the EPA website.

KCI visited the site on 1/31/2018 and 2/1/2018 to collect samples from 36 drinking water outlets in accordance with current criteria described by the Maryland Department of the Environment (MDE) Draft Lead in Drinking Water - Public and Nonpublic Schools, Title 26, Subtitle 16 Lead, Chapter 07.

Samples were submitted to a laboratory for lead in water analysis using current US EPA methodology. The laboratory has been certified by the Maryland Department of the Environment to analyze drinking water for lead.

RESULTS

There are no results of the lead in water analysis at or above 20 parts per billion (ppb). The lead in water sample results for sample collection date 2/1/2018 are shown in Attachment A.

DISCUSSION

Lead is a naturally occurring element that can be harmful to humans when ingested or inhaled, particularly to children under the age of six. Lead can adversely affect the development of children's brain potentially leading to detrimental alterations in intelligence and behavior. Lead has been historically used in plumbing, paint and other building materials. Lead is released into the environment from industrial sources and fuel combustion. Lead may also be found in consumer products (imported candy, medicines, toys, dishes, etc.).

Most lead leaches into drinking water from contact with plumbing components such as faucets and valves made of brass or lead-containing solder. The physical and chemical interaction that occurs between the plumbing and water directly contributes to the amount of lead that is released into the water. Although plumbing components installed prior to the 1990's could contain more lead than newer materials, the amount of lead in the drinking water cannot be predicted by the age of building. The purpose of this regulation is to establish a program to minimize the risk of exposure to lead in drinking water outlets at schools.

Simple steps like keeping your home clean and well-maintained will go a long way in preventing lead exposure. These steps include inspecting and maintaining all painted surfaces to prevent paint deterioration, using only cold water to prepare food and drinks, flushing water outlets used for drinking or food preparation, and cleaning around painted areas where friction can generate dust, such as doors, windows, and drawers. Wipe these areas with a wet sponge or rag to remove paint chips or dust, and wash children's hands, bottles, pacifiers and toys often.

Respectfully Submitted,
KCI Technologies, Inc.



Kamau McAbee
MDE Certified Water Sampler #8281KM

Attachment:

A- Lead in Water Test Summary Table

ATTACHMENT A

Lead in Water Test Summary Table

ATTACHMENT A

Lead in Water Test Summary Table

Contractor: KCI Technologies, Inc.

Certified Laboratory: Microbac Laboratories, Inc.

Sample Results for Wheaton High School

Barcode ID	Room #	Location	Location Notes	Equipment Type	Results (PPB)*	Pass/Fail	Status
LW02602		Hallway	Next To 1400	Cooler	<1.0	Pass	Testing Complete
LW02785	3200	Hallway	Across From	Cooler	<1.0	Pass	Testing Complete
M33112		Hallway	Across From 1605	Cooler	<1.0	Pass	Testing Complete
M33120	1712	Hallway	Outside Of	Cooler	<1.0	Pass	Testing Complete
M33121	1712	Hallway	Outside Of	Cooler	<1.0	Pass	Testing Complete
M33126	1716	Child Development		Cooler	<1.0	Pass	Testing Complete
M33131	1000G	Work Room Administration		Faucet	<1.0	Pass	Testing Complete
M33141	1110	Hallway	outside	Cooler	<1.0	Pass	Testing Complete
M33142	1110	Hallway	outside	Cooler	<1.0	Pass	Testing Complete
M33145	1115	Health Room		Faucet	<1.0	Pass	Testing Complete
M33168	1400	Hallway	Next To	Cooler	<1.0	Pass	Testing Complete
M33179	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33180	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33181	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33182	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33183	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33184	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33186	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33187	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33188	1504	Kitchen Cafeteria		Faucet	<1.0	Pass	Testing Complete
M33189	1504	Kitchen Cafeteria	Across From 1504a	Icemaker	<1.0	Pass	Testing Complete
M33190	1500	Cafeteria	Outside Of 1600	Cooler	<1.0	Pass	Testing Complete
M33191	1500	Cafeteria	Outside Of 1600	Cooler	<1.0	Pass	Testing Complete
M33192	1009	Break Room		Faucet	<1.0	Pass	Testing Complete

Barcode ID	Room #	Location	Location Notes	Equipment Type	Results (PPB)*	Pass/Fail	Status
M33197	1315	Hallway	Across From	Cooler	<1.0	Pass	Testing Complete
M33198	1315	Hallway	Across From	Cooler	<1.0	Pass	Testing Complete
M33201	2702	Hallway	Next To	Cooler	<1.0	Pass	Testing Complete
M33202	2702	Hallway	Next To	Cooler	<1.0	Pass	Testing Complete
M33214		Hallway	Outside	Cooler	<1.0	Pass	Testing Complete
M33215	2026	Hallway	Outside	Cooler	<1.0	Pass	Testing Complete
M33226	2200	Hallway	Left Of	Cooler	<1.0	Pass	Testing Complete
M33227	2200	Hallway	Left Of	Cooler	<1.0	Pass	Testing Complete
M33239	3019	Hallway	Outside	Cooler	<1.0	Pass	Testing Complete
M33251	3200	Hallway	Across From	Cooler	<1.0	Pass	Testing Complete
M33267	2709	Hallway	Next To	Cooler	<1.0	Pass	Testing Complete
M33268	2709	Hallway	Next To	Cooler	<1.0	Pass	Testing Complete

*PPB = parts per billion