

# Montgomery County Public Schools Lead in Drinking Water Testing Report

Sligo Middle School  
1401 Dennis Ave  
Silver Spring, MD 20902

Report Date: May 23, 2026

## LEAD IN DRINKING WATER SAMPLE RESULTS SUMMARY

All Maryland public and nonpublic schools are required to sample all drinking water outlets for the presence of lead pursuant to the Code of Maryland Regulations (COMAR). Montgomery County Public Schools (MCPS) is required to remediate outlets where lead in drinking water concentrations exceed the State Action Level (AL) of 5 parts per billion (ppb). A summary of the lead in water initial samples collected by Environmental Consulting Services, LLC is presented in the table below.

Sampling Date	03/26/2026
# of Outlets Tested	29
# of Outlets $\geq$ 5 ppb	0

## NEXT STEPS

If an initial sample exceeds the AL (5 ppb), the outlet will be shut-down within 24 hours, a follow-up sample collected, and a remedial plan of action developed for this outlet. No additional sampling or remedial actions are required for schools where all initial samples are below the AL.

## HEALTH EFFECTS OF LEAD

Lead can cause serious health problems if too much enters your body from drinking water or other sources. It can cause damage to the brain and kidneys, and can interfere with the production of red blood cells that carry oxygen to all parts of your body. The greatest risk of lead exposure is to infants, young children, and pregnant women. Lead is stored in the bones and it can be released later in life. During pregnancy, the fetus receives lead from the mother's bones, which may affect brain development. Scientists have linked the effects of lead on the brain with lowered IQ in children. Adults with kidney problems and high blood pressure can be affected by low levels of lead more than healthy adults.

## **SOURCES OF HUMAN EXPOSURE TO LEAD**

There are many different sources of human exposure to lead. These include: lead-based paint, lead-contaminated dust or soil, some plumbing materials, certain types of pottery, pewter, brass outlets, food, cosmetics, exposure in the work place and from certain hobbies. According to the Environmental Protection Agency (EPA), 10 to 20 percent of a person's potential exposure to lead may come from drinking water, while for an infant consuming formula mixed with lead-containing water this may increase to 40 to 60 percent.

## **TO REDUCE EXPOSURE TO LEAD IN DRINKING WATER:**

1. Run your water to flush out lead: If water hasn't been used for several hours, run water for 15 to 30 seconds or until it becomes cold or reaches a steady temperature before using it for drinking or cooking.
2. Use cold water for cooking and preparing baby formula: Lead from the plumbing dissolves more easily into hot water.

*\*Please note that boiling the water will not reduce lead levels.*

## **ADDITIONAL INFORMATION**

1. For additional information, please contact Brian Mullikin, Environmental Team Leader, at 240.740.2324 or [brian\\_a\\_mullikin@mcpsmd.org](mailto:brian_a_mullikin@mcpsmd.org).
2. For additional information on reducing lead exposure around your home/building and the health effects of lead, visit EPA's website at [www.epa.gov/lead](http://www.epa.gov/lead).
3. If you are concerned about exposure; contact your local health department or healthcare provider to find out how you can get your child tested for lead.

*Please refer to the attachment(s) for additional water sampling information.*

**Attachment(s)** A – Lead in Water Sample Results Table

**ATTACHMENT A**

**Lead in Water Sample Results Table**

Sampling Results-Sligo Middle School					
Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
LW04714	In kitchen	Faucet, Cold	<1.0	Pass	Testing Complete
LW04715	In kitchen	Faucet, Cold	<1.0	Pass	Testing Complete
LW04716	In kitchen	Faucet, Cold	<1.0	Pass	Testing Complete
LW04717	In kitchen	Faucet, Cold	<1.0	Pass	Testing Complete
LW04718	In kitchen	Faucet, Cold	<1.0	Pass	Testing Complete
LW04719	In work room by office	Faucet, Cold	4.1	Pass	Testing Complete
LW04720	In hallway across from cafeteria	Drinking Water Fountain	<1.0	Pass	Testing Complete
LW04721	In hallway across from cafeteria	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW04722	In health room	Faucet, Cold	3.2	Pass	Testing Complete
LW04728	In hallway next to room 106	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW04729	In hallway next to room 106	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW04734	In break room 111	Faucet, Cold	1.7	Pass	Testing Complete
LW04735	In break room 111	Faucet, Cold	<1.0	Pass	Testing Complete
LW04736	In hallway across from room 113a	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete

Outlet Barcode	Outlet Location	Outlet Type	Initial Results (ppb)	Pass/Fail	Status
LW05285	In hallway next to 110	Faucet, Cold	<1.0	Pass	Testing Complete
LW05286	In media center office	Faucet, Cold	1.4	Pass	Testing Complete
LW05287	In hallway next to room 120	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW05288	In hallway next to room 120	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW05289	In team room TR-C	Faucet, Cold	<1.0	Pass	Testing Complete
LW05290	In hallway across from room 021	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW05291	In hallway across from room 021	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW05295	In hallway next to room 220	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW05335	In hallway next to room 220	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW05336	In team room TR-D	Faucet, Cold	<1.0	Pass	Testing Complete
LW08450	In hallway adjacent to cafeteria	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete
LW12897	In hallway next to room 106	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete
LW12898	In hallway next to 108	Drinking Water Fountain - Cooler/Chiller Style (Refrigerated)	<1.0	Pass	Testing Complete
LW12899	In hallway across room 113A	Bottle Filler/Drinking Fountain Combo Unit - Bottle Filler	<1.0	Pass	Testing Complete

<b>Outlet Barcode</b>	<b>Outlet Location</b>	<b>Outlet Type</b>	<b>Initial Results (ppb)</b>	<b>Pass/Fail</b>	<b>Status</b>
M26119	In kitchen	Faucet, Cold	4.0	Pass	Testing Complete

# Montgomery County Public Schools Lead in Drinking Water Testing Report

**Sligo Middle School  
1401 Dennis Avenue  
Silver Spring, MD 20902**

**Report Date: July 24th, 2023**

## **LEAD IN DRINKING WATER SAMPLE RESULTS SUMMARY**

All Maryland public and nonpublic schools are required to sample all drinking water outlets for the presence of lead pursuant to the Code of Maryland Regulations (COMAR). Montgomery County Public Schools (MCPS) is required to remediate outlets where lead in drinking water concentrations exceed the State Action Level (AL) of 5 parts per billion (ppb). A summary of the lead in water initial samples collected by Inspection Experts Inc. is presented in the table below.

Sampling Date	5/5/23
# of Outlets Tested	29
# of Outlets $\geq$ 5 ppb	3

## **NEXT STEPS**

If an initial sample exceeds the AL (5 ppb), the outlet will be shut-down within 24 hours, a follow up sample collected, and a remedial plan of action developed for this outlet. No additional sampling or remedial actions are required for schools where all initial samples are below the AL.

## **HEALTH EFFECTS OF LEAD**

Lead can cause serious health problems if too much enters your body from drinking water or other sources. It can cause damage to the brain and kidneys, and can interfere with the production of red blood cells that carry oxygen to all parts of your body. The greatest risk of lead exposure is to infants, young children, and pregnant women. Lead is stored in the bones and it can be released later in life. During pregnancy, the fetus receives lead from the mother's bones, which may affect brain development. Scientists have linked the effects of lead on the brain with lowered IQ in children. Adults with kidney problems and high blood pressure can be affected by low levels of lead more than healthy adults.

## **SOURCES OF HUMAN EXPOSURE TO LEAD**

There are many different sources of human exposure to lead. These include: lead-based paint, lead-contaminated dust or soil, some plumbing materials, certain types of pottery, pewter, brass outlets, food, cosmetics, exposure in the workplace and from certain hobbies. According to the Environmental Protection Agency (EPA), 10 to 20 percent of a person's potential exposure to lead may come from drinking water, while for an infant consuming formula mixed with lead containing water this may increase to 40 to 60 percent.

## **TO REDUCE EXPOSURE TO LEAD IN DRINKING WATER:**

1. Run your water to flush out lead: If water hasn't been used for several hours, run water for 15 to 30 seconds or until it becomes cold or reaches a steady temperature before using it for drinking or cooking.
2. Use cold water for cooking and preparing baby formula: Lead from the plumbing dissolves more easily into hot water.

*\*Please note that boiling the water will not reduce lead levels.*

## **ADDITIONAL INFORMATION**

1. For additional information, please contact Brian Mullikin, Environmental Team Leader, at 240.740.2324 or [brian\\_a\\_mullikin@mcpsmd.org](mailto:brian_a_mullikin@mcpsmd.org).
2. For additional information on reducing lead exposure around your home/building and the health effects of lead, visit EPA's website at [www.epa.gov/lead](http://www.epa.gov/lead).
3. If you are concerned about exposure; contact your local health department or healthcare provider to find out how you can get your child tested for lead.

*Please refer to the attachment(s) for additional water sampling information.*

## **Attachment(s):**

A - Lead in Water Sample Results Table

**ATTACHMENT A**

**Lead in Water Sample Results Table**

## Sampling Results for Sligo MS

Outlet Barcode	Outlet Location	Outlet Type	Initials Results (ppb)	Pass/Fail	Status
LW04714	In kitchen	Kitchen Sink	<1.0	Pass	Testing Complete
LW04715	In kitchen	Kitchen Sink	3.7	Pass	Testing Complete
LW04716	In kitchen	Kitchen Sink	<1.0	Pass	Testing Complete
LW04717	In kitchen	Kitchen Sink	<1.0	Pass	Testing Complete
LW04718	In kitchen	Kitchen Sink	<1.0	Pass	Testing Complete
LW04719	In work room by office	Teachers Lounge Sink	<1.0	Pass	Testing Complete
LW04720	In hallway across from café	Drinking Fountain	<1.0	Pass	Testing Complete
LW04721	In hallway across from café	Drinking Fountain	<1.0	Pass	Testing Complete
LW04722	In health room	Nurses Office Sink	9.2	Fail	Remediation Action Plan
LW04728	In hallway next to room 106	Drinking Fountain	<1.0	Pass	Testing Complete
LW04729	In hallway next to room 106	Drinking Fountain	<1.0	Pass	Testing Complete
LW04734	In break room 111	Teachers Lounge Sink	<1.0	Pass	Testing Complete
LW04735	In break room 111	Teachers Lounge Sink	<1.0	Pass	Testing Complete
LW04736	In hallway across from room 113a	Drinking Fountain	<1.0	Pass	Testing Complete
LW05287	In hallway next to room 120	Drinking Fountain	<1.0	Pass	Testing Complete

<b>Outlet Barcode</b>	<b>Outlet Location</b>	<b>Outlet Type</b>	<b>Initials Results (ppb)</b>	<b>Pass/Fail</b>	<b>Status</b>
LW05288	In hallway next to room 120	Drinking Fountain	<1.0	Pass	Testing Complete
LW05289	In team room TR-C	Teachers Lounge Sink	<1.0	Pass	Testing Complete
LW05290	In hallway across from room 021	Drinking Fountain	<1.0	Pass	Testing Complete
LW05291	In hallway across from room 021	Drinking Fountain	<1.0	Pass	Testing Complete
LW05294	In team room TR-A	Teachers Lounge Sink	<1.0	Pass	Testing Complete
LW05295	In hallway next to room 220	Drinking Fountain	<1.0	Pass	Testing Complete
LW05335	In hallway next to room 220	Drinking Fountain	<1.0	Pass	Testing Complete
LW05336	In team room TR-D	Teachers Lounge Sink	<1.0	Pass	Testing Complete
LW08450	In hallway adjacent to cafeteria	Drinking Fountain	<1.0	Pass	Testing Complete
M26118	In kitchen by cafeteria	Kitchen Sink	6.3	Fail	Remediation Action Plan
M26119	In kitchen	Kitchen Sink	9.2	Fail	Remediation Action Plan
LW05258	In team room TR-B	Teachers Lounge Sink	<1.0	Pass	Testing Complete
LW12897	In hallway next to room 106	Drinking Fountain	<1.0	Pass	Testing Complete
LW12899	In hallway across room 113A	Drinking Fountain	<1.0	Pass	Testing Complete

# Montgomery County Public Schools Lead in Drinking Water Testing Report

**Sligo Middle School  
1401 Dennis Ave.  
Silver Spring, MD 20902**

**Report Date: April 14th, 2020**

## **LEAD IN DRINKING WATER SAMPLE RESULTS SUMMARY**

All Maryland public and nonpublic schools are required to sample all drinking water outlets for the presence of lead pursuant to the Code of Maryland Regulations (COMAR). Montgomery County Public Schools (MCPS) is required to remediate outlets where lead in drinking water concentrations exceed the Montgomery County Action Level (AL) of 5 parts per billion (ppb). A summary of the lead in water initial samples collected by SaLUT are presented in the table below.

Sampling Date	2/19/2020
# of Outlets Tested	35
# of Outlets $\geq$ 5 ppb	2

## **NEXT STEPS**

If an initial sample exceeds the AL (5 ppb), the outlet will be immediately shut-down, a follow-up sample collected, and a remedial plan of action developed for this outlet. No additional sampling or remedial actions are required for schools where all initial samples are below the AL.

## **HEALTH EFFECTS OF LEAD**

Lead can cause serious health problems if too much enters your body from drinking water or other sources. It can cause damage to the brain and kidneys, and can interfere with the production of red blood cells that carry oxygen to all parts of your body. The greatest risk of lead exposure is to infants, young children, and pregnant women. Lead is stored in the bones and it can be released later in life. During pregnancy, the fetus receives lead from the mother's bones, which may affect brain development. Scientists have linked the effects of lead on the brain with lowered IQ in children. Adults with kidney problems and high blood pressure can be affected by low levels of lead more than healthy adults.

## **SOURCES OF HUMAN EXPOSURE TO LEAD**

There are many different sources of human exposure to lead. These include: lead-based paint, lead-contaminated dust or soil, some plumbing materials, certain types of pottery, pewter, brass fixtures, food, cosmetics, exposure in the work place and from certain hobbies. According to the Environmental Protection Agency (EPA), 10 to 20 percent of a person's potential exposure to lead may come from drinking water, while for an infant consuming formula mixed with lead-containing water this may increase to 40 to 60 percent.

### **TO REDUCE EXPOSURE TO LEAD IN DRINKING WATER:**

1. Run your water to flush out lead: If water hasn't been used for several hours, run water for 15 to 30 seconds or until it becomes cold or reaches a steady temperature before using it for drinking or cooking.
2. Use cold water for cooking and preparing baby formula: Lead from the plumbing dissolves more easily into hot water.

*\*Please note that boiling the water will not reduce lead levels.*

### **ADDITIONAL INFORMATION**

1. For additional information, please contact Brian Mullikin, Environmental Team Leader, at 240.740.2324 or [brian\\_a\\_mullikin@mcpsmd.org](mailto:brian_a_mullikin@mcpsmd.org).
2. For additional information on reducing lead exposure around your home/building and the health effects of lead, visit EPA's website at [www.epa.gov/lead](http://www.epa.gov/lead).
3. If you are concerned about exposure; contact your local health department or healthcare provider to find out how you can get your child tested for lead.

*Please refer to the attachment(s) for additional water sampling information.*

**Attachment(s)** A – Lead in Water Sample Results Table

**ATTACHMENT A**

**Lead in Water Sample Results Table**

## Sampling Results for Sligo MS

Fixture Barcode	Fixture Location	Fixture Type	Initial Results (ppb)	Pass/Fail	Follow up Results (ppb)	Status
LW04714	In kitchen by kitchen	Kitchen Sink	1.0	Pass	N/A	Testing Complete
LW04715	In kitchen by kitchen	Kitchen Sink	<1	Pass	N/A	Testing Complete
LW04716	In kitchen by kitchen	Kitchen Sink	<1	Pass	N/A	Testing Complete
LW04717	In kitchen by kitchen	Kitchen Sink	<1	Pass	N/A	Testing Complete
LW04718	In kitchen by kitchen	Kitchen Sink	2.0	Pass	N/A	Testing Complete
LW04719	In work room by office	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete
LW04720	In hallway across from café	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW04721	In hallway across from café	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW04722	In health room	Nurses Office Sink	5.6	Fail	3.2	Remediation Action Plan
LW04723	In classroom 102	Classroom Sink	1.1	Pass	N/A	Testing Complete
LW04724	In classroom 102	Classroom Sink	<1	Pass	N/A	Testing Complete
LW04725	In classroom 101	Classroom Sink	<1	Pass	N/A	Testing Complete
LW04728	In hallway next to room 106	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW04729	In hallway next to room 106	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW04734	In break room 111	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete
LW04735	In break room 111	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete
LW04736	In hallway across from room 113a	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05284	In classroom 113B	Classroom Sink	<1	Pass	N/A	Testing Complete
LW05285	In team room TR-B by team room	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete
LW05286	In work room by media center	Classroom Sink	6.1	Fail	2.6	Remediation Action Plan
LW05287	In hallway next to room 120	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05288	In hallway next to room 120	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05289	In team room TR-C	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete

LW05290	In hallway across from room 021	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05291	In hallway across from room 021	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05292	In hallway across from room 025	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05293	In hallway across from room 025	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05294	In team room TR-A	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete
LW05295	In hallway next to room 220	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05335	In hallway next to room 220	Drinking Fountain	<1	Pass	N/A	Testing Complete
LW05336	In team room TR-D	Teachers Lounge Sink	<1	Pass	N/A	Testing Complete
M26118	In kitchen by cafeteria	Kitchen Sink	1.7	Pass	N/A	Testing Complete
M26119	In kitchen by kitchen	Kitchen Sink	<1	Pass	N/A	Testing Complete
M26139	In work room 101	Classroom Sink	<1	Pass	N/A	Testing Complete
LW08450	In hallway adjacent to cafeteria	Drinking Fountain	<1	Pass	N/A	Testing Complete



## Montgomery County Public Schools Lead in Drinking Water Post-Remediation Follow-Up Testing 2019

August 30, 2019

### Executive Summary:

#### Sligo Middle School

1401 Dennis Avenue

Silver Spring, Maryland 20902

Round of Testing:	Post-Remediation Follow-up
Sample Date	1/29/19
# of Outlets Tested:	2
# of Outlets $\geq 5$ ppb:	0
Low Value (ppb):	3.5
High Value (ppb):	3.6

### Project Status

**Testing Complete:** Post-remediation follow-up testing completed for following rooms:

Break Room 111 - Outlet (LW04731) will be placed back into service

Kitchen Cafeteria - Outlet (M26118) will be placed back into service



August 30, 2019

Mr. Brian Mullikin, MS  
Environmental Team Leader  
Montgomery County Public Schools  
8301 Turkey Thicket Dr., Bldg A, 1st Floor  
Gaithersburg, Maryland 20879

Re: Lead in Water Post-Remediation Follow-up Testing Service

**Location: Sligo Middle School**

1401 Dennis Avenue  
Silver Spring, Maryland 20902

Dear Mr. Mullikin:

KCI Technologies, Inc. (KCI) is pleased to submit the following report to the Montgomery County Public Schools (MCPS) for completion of the post-remediation follow-up lead in water testing at Sligo Middle School, located at 1401 Dennis Avenue in Silver Spring, Maryland 20902.

**SCOPE OF SERVICES**

Two drinking water outlets were remediated at Sligo Middle School due to initial lead levels that exceeded the lead action level of 5 parts per billion (ppb). KCI Technologies, Inc. conducted lead in water post-remediation follow-up testing in accordance with the Maryland Code of Regulations (COMAR) 26.16.07 - Lead in Drinking Water - Public and Nonpublic Schools.

KCI Technologies, Inc. visited the site on 1/29/19 and 1/29/19 to collect post-remediation follow-up samples from 2 drinking water outlets that had been replaced. Samples were submitted to a laboratory for lead in water analysis using current US EPA methodology. The laboratory has been certified by the Maryland Department of the Environment to analyze drinking water for lead.

**RESULTS**

The initial, flush, and post-remediation follow-up results are highlighted in the summary table below:

Barcode ID	Room Number	Location	Notes	Equipment Type	Initial (ppb)	Flush (ppb)	Post-Remediation Follow-up (ppb)	Post-Remediation Follow-up Pass/Fail	Status
LW04731	111	Break Room		Faucet	50.6	2.9	3.6	Pass	Post-remediation follow-up testing complete. Outlet will be placed back into service
M26118		Kitchen Cafeteria		Faucet	29	12.7	3.5	Pass	Post-remediation follow-up testing complete. Outlet will be placed back into service

## **DISCUSSION**

Lead is a naturally occurring element that can be harmful to humans when ingested or inhaled, particularly to children under the age of six. Lead can adversely affect the development of children's brain potentially leading to detrimental alterations in intelligence and behavior. Lead has been historically used in plumbing, paint and other building materials. Lead is released into the environment from industrial sources and fuel combustion. Lead may also be found in consumer products (imported candy, medicines, toys, dishes, etc.).

Most lead leaches into drinking water from contact with plumbing components such as faucets and valves made of brass or lead-containing solder. The physical and chemical interaction that occurs between the plumbing and water directly contributes to the amount of lead that is released into the water. Although plumbing components installed prior to the 1990's could contain more lead than newer materials, the amount of lead in the drinking water cannot be predicted by the age of building. The purpose of this regulation is to establish a program to minimize the risk of exposure to lead in drinking water outlets at schools. The Environmental Protection Agency (EPA) developed the 3T's (Training, Testing, and Telling) to assist schools in reducing the lead concentrations in their drinking water. More information about 3T's can be found on the EPA website.

Simple steps like keeping your home clean and well-maintained will go a long way in preventing lead exposure. These steps include inspecting and maintaining all painted surfaces to prevent paint deterioration, using only cold water to prepare food and drinks, flushing water outlets used for drinking or food preparation, and cleaning around painted areas where friction can generate dust, such as doors, windows, and drawers. Wipe these areas with a wet sponge or rag to remove paint chips or dust, and wash children's hands, bottles, pacifiers and toys often.

---

Respectfully Submitted,  
KCI Technologies, Inc.



Kamau McAbee  
MDE Certified Water Sampler #8281KM  
KCI Job #1214634186



## Montgomery County Public Schools Lead in Drinking Water Testing 2018

April 27, 2018

### Executive Summary:

#### Sligo Middle School

1401 Dennis Avenue

Silver Spring, Maryland 20902

Round of Testing:	Initial
# of Outlets Tested:	41
# of Outlets $\geq 20$ ppb:	2
Low Value (ppb):	<1.0
High Value (ppb):	50.6
Follow-Up Testing Required (Samples $\geq 20$ ppb):	Break Room (50.6 ppb) Kitchen (29.0 ppb)

Round of Testing:	Follow-Up - 30 sec draw
# of Outlets Tested:	2

### Project Status:

#### Testing Complete: Remediation Plan

Break Room - Replace fixture (LW04731), in addition to supply line and valve located under sink

Kitchen - Replace fixture (M26118), in addition to supply line and valve located under sink



April 27, 2018

Mr. Brian Mullikin, MS  
Environmental Team Leader  
Montgomery County Public Schools  
Division of Maintenance  
Gaithersburg, Maryland 20879

Re: Drinking Water Testing

KCI Job #1214634186

**Location: Sligo Middle School**

1401 Dennis Avenue  
Silver Spring, Maryland 20902

Dear Mr. Mullikin:

KCI Technologies, Inc. (KCI) is pleased to submit the following report to the Montgomery County Public Schools (MCPS) for completion of initial and follow-up lead in water testing at Sligo Middle School, located at 1401 Dennis Avenue in Silver Spring, Maryland 20902.

**SCOPE OF SERVICES**

KCI conducted lead in water testing at Sligo Middle School in accordance with the Environmental Protection Agency (EPA) and Maryland House Bill (HB) 270. State regulation established an action level of 20 parts per billion (ppb) to evaluate lead levels in school buildings, a concentration EPA recommends that schools take action to reduce lead below this action level. Maryland requires periodic testing for the presence of lead in drinking water in occupied public and nonpublic school buildings. EPA developed the 3T's (Training, Testing, and Telling) to assist schools in reducing the lead concentrations in their drinking water. More information about 3T's can be found on the EPA website.

KCI visited the site on 2/21/2018 and 2/22/2018 to collect samples from 41 drinking water outlets in accordance with current criteria described by the Maryland Department of the Environment (MDE) Draft Lead in Drinking Water - Public and Nonpublic Schools, Title 26, Subtitle 16 Lead, Chapter 07. On 4/11/2018 and 4/13/2018, two 30 second follow-up samples were collected.

Samples were submitted to a laboratory for lead in water analysis using current US EPA methodology. The laboratory has been certified by the Maryland Department of the Environment to analyze drinking water for lead.

---

## **RESULTS**

There were two results of the lead in water analysis at or above 20 parts per billion (ppb) and subsequent follow up 30 second results are highlighted in the summary table below:

<b>Barcode ID</b>	<b>Sample Location</b>	<b>Date Collected</b>	<b>Initial Sample Result (ppb)</b>	<b>Date Collected</b>	<b>30 Second Follow Up Sample Result (ppb)</b>
LW04731	Faucet - Break Room	2/22/2018	50.6	4/11/2018 and 4/13/2018	2.9
M26118	Faucet - Kitchen	2/22/2018	29.0	4/11/2018 and 4/13/2018	12.7

The initial lead in water sample results (2/22/2018) and 30 second follow up results (4/11/2018 and 4/13/2018) are shown in Attachment A.

## **DISCUSSION**

Lead is a naturally occurring element that can be harmful to humans when ingested or inhaled, particularly to children under the age of six. Lead can adversely affect the development of children's brain potentially leading to detrimental alterations in intelligence and behavior. Lead has been historically used in plumbing, paint and other building materials. Lead is released into the environment from industrial sources and fuel combustion. Lead may also be found in consumer products (imported candy, medicines, toys, dishes, etc.).

Most lead leaches into drinking water from contact with plumbing components such as faucets and valves made of brass or lead-containing solder. The physical and chemical interaction that occurs between the plumbing and water directly contributes to the amount of lead that is released into the water. Although plumbing components installed prior to the 1990's could contain more lead than newer materials, the amount of lead in the drinking water cannot be predicted by the age of building. The purpose of this regulation is to establish a program to minimize the risk of exposure to lead in drinking water outlets at schools.

Simple steps like keeping your home clean and well-maintained will go a long way in preventing lead exposure. These steps include inspecting and maintaining all painted surfaces to prevent paint deterioration, using only cold water to prepare food and drinks, flushing water outlets used for drinking or food preparation, and cleaning around painted areas where friction can generate dust, such as doors, windows, and drawers. Wipe these areas with a wet sponge or rag to remove paint chips or dust, and wash children's hands, bottles, pacifiers and toys often.

---

Respectfully Submitted,  
KCI Technologies, Inc.



Kamau McAbee  
MDE Certified Water Sampler #8281KM

Attachment:

A- Lead in Water Test Summary Table

# ATTACHMENT A

## Lead in Water Test Summary Table

ATTACHMENT A

Lead in Water Test Summary Table

**Contractor:** KCI Technologies, Inc.

**Certified Laboratory:** Microbac Laboratories, Inc.

Initial Sample Results for Sligo Middle School

Barcode ID	Room #	Location	Location Notes	Equipment Type	Results (PPB)*	Pass/Fail	Status
LW04714		Kitchen		Faucet	1.7	Pass	Testing Complete
LW04715		Kitchen		Faucet	1.3	Pass	Testing Complete
LW04716		Kitchen		Faucet	1.0	Pass	Testing Complete
LW04717		Kitchen		Faucet	<1.0	Pass	Testing Complete
LW04718		Kitchen		Faucet	3.2	Pass	Testing Complete
LW04719		Work Room Office		Faucet	1.0	Pass	Testing Complete
LW04720		Hallway	Across From Café	Cooler	<1.0	Pass	Testing Complete
LW04721		Hallway	Across From Café	Cooler	<1.0	Pass	Testing Complete
LW04722		Health Room		Faucet	2.4	Pass	Testing Complete
LW04723	102	Classroom		Faucet	1.7	Pass	Testing Complete
LW04724	102	Classroom		Faucet	<1.0	Pass	Testing Complete
LW04725	101	Classroom		Faucet	<1.0	Pass	Testing Complete
LW04726	104	Art		Faucet	4.5	Pass	Testing Complete
LW04727	104	Art		Faucet	<1.0	Pass	Testing Complete
LW04728		Hallway	Next To Room 106	Cooler	<1.0	Pass	Testing Complete
LW04729		Hallway	Next To Room 106	Cooler	<1.0	Pass	Testing Complete
LW04730	111	Break Room		Faucet	2.8	Pass	Testing Complete
LW04731	111	Break Room		Faucet	50.6	Fail	Follow-up Testing Needed
LW04732	111	Break Room		Faucet	5.0	Pass	Testing Complete
LW04733	111	Break Room		Faucet	2.8	Pass	Testing Complete
LW04734	111	Break Room		Faucet	1.6	Pass	Testing Complete
LW04735	111	Break Room		Faucet	1.2	Pass	Testing Complete
LW04736		Hallway	Across From Room 113a	Cooler	<1.0	Pass	Testing Complete
LW05283	113	Classroom		Faucet	4.8	Pass	Testing Complete
LW05284	113B	Classroom		Faucet	1.6	Pass	Testing Complete
LW05285	TR-B	Team Room		Faucet	<1.0	Pass	Testing Complete
LW05286		Work Room Media Center		Faucet	2.4	Pass	Testing Complete

Barcode ID	Room #	Location	Location Notes	Equipment Type	Results (PPB)*	Pass/Fail	Status
LW05287		Hallway	Next To Room 120	Cooler	<1.0	Pass	Testing Complete
LW05288		Hallway	Next To Room 120	Cooler	<1.0	Pass	Testing Complete
LW05289	TR-C	Team Room		Faucet	2.1	Pass	Testing Complete
LW05290		Hallway	Across From Room 021	Cooler	<1.0	Pass	Testing Complete
LW05291		Hallway	Across From Room 021	Cooler	<1.0	Pass	Testing Complete
LW05292		Hallway	Across From Room 025	Cooler	<1.0	Pass	Testing Complete
LW05293		Hallway	Across From Room 025	Cooler	<1.0	Pass	Testing Complete
LW05294	TR-A	Team Room		Faucet	1.1	Pass	Testing Complete
LW05295		Hallway	Next To Room 220	Cooler	<1.0	Pass	Testing Complete
LW05335		Hallway	Next To Room 220	Cooler	<1.0	Pass	Testing Complete
LW05336	TR-D	Team Room		Faucet	<1.0	Pass	Testing Complete
M26118		Kitchen		Faucet	29.0	Fail	Follow-up Testing Needed
M26119		Kitchen		Faucet	1.0	Pass	Testing Complete
M26139	101	Work Room		Faucet	<1.0	Pass	Testing Complete

\*PPB = Parts per billion

**Contractor:** KCI Technologies, Inc.

**Certified Laboratory:** Microbac Laboratories, Inc.

Follow Up Sample Results for Sligo Middle School

Barcode ID	Room #	Location	Equipment Type	Initial Draw (2nd) (PPB)	Initial Draw (3rd) (PPB)	30 Second Draw (PPB)*	Status
LW04731	111	Break Room	Faucet	N/A	121	2.9	Remediation required – replace fixture, in addition to supply line and valve located under sink
M26118		Kitchen	Faucet	11.4	26.5	12.7	Remediation required – replace fixture, in addition to supply line and valve located under sink

\*PPB = Parts per billion

Note: Fixture(s) with elevated test results were immediately removed from service. Subsequent 2nd and 3rd round testing was performed on these fixture(s) for further diagnostics for remediation. Because the fixture was shut off after the first test, the subsequent test results may not be representative of an in-use fixture because of stagnant water in the supply line and the operation of shut off valves prior to the tests. All fixtures with elevated test results are to be remediated. After remediation, post remediation testing will be conducted before the fixture is returned to service.