

Division of Maintenance



8301 Turkey Thicket Drive, Building A, First Floor
Gaithersburg, MD 20879
(240) 740-2500

Attachment A

MONTGOMERY COUNTY PUBLIC SCHOOLS AVAILABILITY OF ASBESTOS MANAGEMENT PLAN

In October 1986, the U.S. Congress enacted the Asbestos Hazard Emergency Response Act (AHERA). Under this law, comprehensive regulations were developed to address asbestos problems in public and private elementary and secondary schools. These regulations require most schools to inspect for friable and non-friable asbestos, develop Asbestos Management Plans that address asbestos hazards in school buildings, and implement response actions in a timely manner.

These regulations assign schools many new responsibilities. Our program for fulfilling these responsibilities is outlined in our Asbestos Management Plan. This plan contains information on the designated person, architect's or engineer's letter, notification process, assurances, and dated copies of the annual notification.

For new buildings, those completed after October 12, 1988, our "management plan" consists of the exclusion documentation including this notification. This documentation means that, to our knowledge, no asbestos-containing building materials were used or specified for use in this building.

You can review this plan during normal business hours without cost or restriction.

If you have questions, please contact Mr. John Conaway, environmental health specialist, Environmental Services/Indoor Air Quality Unit, Division of Maintenance, at 240-740-2331 or John_D_Conaway@mcpsmd.org.

Division of Maintenance



8301 Turkey Thicket Drive, Building A, First Floor
Gaithersburg, MD 20879
(240) 740-2500

Attachment B

MONTGOMERY COUNTY PUBLIC SCHOOLS DISPONIBILIDAD DE PLAN DE CONTROL DE ASBESTO

En octubre 1986, el Congreso de los Estados Unidos promulgó la legislación Asbestos Hazard Emergency Response Act (AHERA). Bajo esta ley, se desarrollaron regulaciones integrales para abordar problemas de asbesto en escuelas elementales y secundarias públicas y privadas. Estas regulaciones exigen que la mayoría de las escuelas hagan inspecciones de asbesto/amianto friable y no friable, desarrollen planes de control de asbesto que aborden los riesgos de asbesto en edificios escolares, e implementen acciones para responder de manera oportuna.

Estas regulaciones asignan a las escuelas muchas responsabilidades nuevas. Nuestro programa para cumplir con estas responsabilidades se detalla en nuestro plan de control de asbesto. Este plan contiene información sobre la persona designada, la carta del arquitecto o del ingeniero, el proceso de notificación, las garantías, y copias fechadas de la notificación anual.

Para edificios nuevos, aquellos que se teminaron de construir después del 12 de octubre, 1988, nuestro "plan de control" consiste de la documentación de exclusión, incluyendo esta notificación. Esta documentación significa que, a nuestro conocimiento, no se usaron o especificaron materiales de construcción que contenían asbesto para uso en este edificio.

Usted puede revisar este plan durante el horario laboral normal sin costo o restricción.

Si tiene preguntas, comuníquese con el Sr. John Conaway, Especialista en Salud Ambiental, Environmental Services/Indoor Air Quality Unit, Division of Maintenance, al 240-740-2331 o John_D_Conaway@mcpsmd.org.