

## Montgomery County Public Schools

### 2018 School Facilities Assessment

School Number **799**  
 School Name **Stephen Knolls School**  
 School Type **Special Education**  
 Year Built\* **1958**  
 Year of Last Renovation\* **1979**  
 GSF\* **48,872**



#### Building Level - Key Facility Indicators



#### Infrastructure - Facility Condition

● A10 Foundations	n/a	● C20 Stairs	● D50 Electrical
n/a A20 Basement	●	● C30 Interior Finishes	● E10 Equipment
● B10 Superstructure	n/a	● D10 Conveying Systems	● E20 Furnishings
● B20 Exterior Enclosure	●	● D20 Plumbing	● F10 Special Construction
● B30 Roofing	●	● D30 HVAC	
● C10 Interior Construction	●	● D40 Fire Protection	

#### Building Characteristics

Building Quality	Indoor Environment
● Classroom Shape*	● Temperature Control
● IMC Size*	● Humidity Control
● Cafeteria Size*	● Natural Light
● Corridor*	● Acoustic Features
	● Building-Level Power Delivery

\*indicates that underlying data was provided by MCPS not collected by FEA.

Information Sources:	(References)
----------------------	--------------