

Montgomery County Public Schools

2018 School Facilities Assessment

School Number **995**
 School Name **Radnor Center**
 School Type **Other Education**
 Year Built* **0**
 Year of Last Renovation* **0**
 GSF* **36,663**



Building Level - Key Facility Indicators



Infrastructure - Facility Condition

● A10 Foundations	n/a	● C20 Stairs	● D50 Electrical
n/a A20 Basement	● C30 Interior Finishes	● E10 Equipment	
● B10 Superstructure	n/a D10 Conveying Systems	● E20 Furnishings	
● B20 Exterior Enclosure	● D20 Plumbing	● F10 Special Construction	
● B30 Roofing	● D30 HVAC		
● C10 Interior Construction	n/a D40 Fire Protection		

Building Characteristics

Building Quality	Indoor Environment
● Classroom Shape*	● Temperature Control
● IMC Size*	● Humidity Control
● Cafeteria Size*	● Natural Light
● Corridor*	● Acoustic Features
	● Building-Level Power Delivery

*indicates that underlying data was provided by MCPS not collected by FEA.

Information Sources:	(References)
----------------------	--------------